Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 13, 1989

Mr. Armando L. Suarez 2440 SW 87 Ave. Miami, FL 33165

Dear Mr. Suarez:

Your Model 600, 308 Cal. rifle, S.N. 33832 has been received and examined.

This rifle has been under a recall program since 1979. The trigger assembly will be changed at no charge to you. However, the broken stock is another matter. Since we no longer produce the particular rifle, and have not for some years, we have no stocks to use for replacement. We can, I believe, repair the stock. There will be a charge for this of course.

We will do the trigger replacement, but will wait for your go ahead before we repair the stock.

We will await your reply at your earliest convenience.

Sincerely,

R.L. St. John

Product Service

RLSJ/rld