

*Remington.*



Dec. 17 ms 3470.11  
Hold for reply  
R89-18933  
G. Hutton  
B. Ericson

## REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

August 15, 1989

Mr. Ladell Sump  
104 Lindsey  
Bay City, TX 77414

Dear Mr. Sump:

Examination has been completed on the Mohawk 600 222 Rem. caliber rifle, serial number 6651197, that you returned to us a short time ago because it had fired when the bolt was closed.

The returned firearm, which was produced in August of 1973, has been thoroughly examined and found to contain a recall replacement trigger assembly, as indicated by a letter "V" stamped on the trigger finger piece.

The general condition of the gun appeared to be very good. In going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of your rifle and trigger assembly could not produce any malfunctions. Many attempts were made to cause the rifle to fire upon bolt closing, to no avail. All tolerances and dimensions were found to be normal. Trigger pull was measured to be five (5) pounds, and the sear lift with the safety in the "on-safe" position was well within specifications at .011".

Since we found the firearm to be correct and to function normally in every respect, we are prepared to return it to you in its present condition. However, if you desire, we will install a new trigger assembly at no-charge, as a gesture of good-will, if it will restore your confidence in the rifle. We will await your decision and reply.