

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 91-25984

INITIAL

CUSTOMER ORDER NO.

LCS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

BDL

12/10/91

12/12/91

PF 6-B5

B6712840

700

6MM

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

TATUM, JULIEN
PO BOX 603
UNIVERSITY
USA

MS 38677

SHIP TO:

TATUM, JULIEN
135 LEIGHTON RD
OXFORD
USA

MS

38655

CUST NO: 054693 C.O.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

1) "on occasion this rifle will discharge while pushing the safety from the on position to the off position".

2) accuracy is unacceptable 3"-4" groups at 100 yards

MAIN FAULT

1) Insert of trigger assembly has somehow become rusted. Internal trigger parts are not moving freely nor properly.
2) Rifle will have to be gallery tested to determine.

PARTS

COMMENTS

1) Replace trigger assembly at no-charge as gesture of good-will.

2) Have gallery test accuracy of rifle

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PAT

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 RE