

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

February 13, 1985

Mr. Billy Y. Turner
720 Palestine St.
Jacksonville, Texas 75766

Dear Mr. Turner:

Your letter of January 19, 1985 that was addressed to our Bridgeport, Connecticut facility, regarding the accidental firing you have experienced when releasing the safety on your Model 700 7mm Rem. Mag. caliber rifle, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described, as it is not characteristic of the Model 700 rifle.

Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger as the safety is being moved.

Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Company, Inc.
Attn: J.A. Stekl, Supervisor
Product Service
Ilion, New York 13357

Upon receipt, we will thoroughly examine the rifle and, if it is found to be factory faulty, any necessary corrections will be made on a no-charge basis.

Thank you for bringing this matter to our attention and for affording us this opportunity to be of service.

Sincerely,

J.A. Stekl, Supervisor
Product Service