



NOV 2 2 1983

J. A. STEKL

Remington Arms Company, Inc. Arms Service Division Ilion, New York 13357

Dear Sir,

I recently purchased a Remington Model 700 BDL rifle in a 25-06 caliber. The serial number is B6425005. I am very disappointed that the bolt lock type safety is no longer used on this rifle. My style of huntting requires this type of safety.

I have several Model 700 rifles and it appears that the bolt lock safety switch on the older rifles will inter-change with the newer type safety switch. If this is true, I would like to purchase the bolt lock type safety switch for my new Remington 25-06 Rifle.

You can either bill me for the switch or mail it COD.

Very truely yours, Max O. Usrey 111

100000, 11. U.S. U.S. U.S. U.S. CONSCIENCES

5530 Parkhill Court Baton Rouge, La. 70816 Nov. 16, 1983