

TRACKING # TLW0010
PROJECT #241095

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-	
				RDS. FIRED	TOTAL RDS.
JW/SW	9/9/00	HEADSPACE	MIN. +.002		
JW/SW	9/9/00	PROOF, HEADSPACE	PROOF, INSPECT, HEADSPACE MIN. +.002 & PROOF STAMP	1	1
JA/BL/JC	9/9/00	Trigger Pulls			
JA/BL/JC	9/9/00	Sear/Trigger Engagement/Sear LIFT			
JC	9/9/00	Inspection			
JW/SW	9-10-00	SAAMI DROP TEST	JAR OFF, DROP, ROTATION		
JA/BL/SW	9-11-00	Trigger Pull/Engagement	AFTER SAAMI Drop (See TLW0010AR)		
JA/BL/SW	9-11-00	Inspection	No Cracks		
WRT	9-11-00	MECHANICAL BUT HEAD	NO INDICATIONS		
JW/SW	9-13-00	EXTENDED JAR OFF	6" - Plastic Insert Cracked on Barrel Horizontal Right Side of stock up - stopped test on 18"		
JW/SW	9-14-00		Replace plastic insert #1308-2		
JW/SW	9-14-00	TRIGGER PULL	AVERAGE 4.125 ENGAGEMENT .0213		
JW/SW	9-14-00	EXTENDED JAR OFF	CONTINUED 18" - 24" - 48" finished, INSPECTED		
JW/SW	9-14-00	TRIGGER PULL/ENGAGEMENT	AFTER EXTENDED JAR OFF		
JW/SW	9-15-00	EXTENDED DROP TEST	BROKE FRONT TWO SCOPE RAIL SCREWS ON 72" EXTENDED DROP TEST ON BARREL HORIZONTAL, LEFT SIDE OF STOCK UP		
JW	9-20-00		REPLACED FRONT TWO SCOPE RAIL SCREWS & SCOPE		
JW/SW	9-21-00	Extended Drop Test	Bolt Plug SEPARATED FROM INSERT on barrel horizontal right side of stock up		
JW/SW	9-26-00		Replaced w/ one from B27 bolt plug assembly		
JW/SW	9-28-00	EXTENDED DROP TEST	BROKE PLASTIC INSERT ON 72" EXTENDED DROP TEST BARREL HORIZONTAL, BOTTOM OF STOCK UP		
JW/SW	9-28-00		REPLACED PLASTIC INSERT		
JW/SW	9-28-00	TRIGGER PULL/ENGAGEMENT	SET TO SPEC, AFTER REPLACING INSERT		
JW/SW	9-28-00	EXTENDED DROP TEST	CONTINUED TEST @ 72" COMPLETE		
JW/SW	9-28-00	Inspection	Scope bent		
JW/SW	9-29-00	Extended Rotation Test	Complete		
JA/BL	10-2-00	Trigger Pull	Average 4.66		
JA/BL	10-2-00	Engagement	.0215		

Forms

BARBER - 5.22.06r0003108

139