

RECEIVING AND ESTIMATING REPORT

COMMENTS

TIAL CUSTOMER ORDER NO.

JM

TE RECEIVED 4/19/91 DATE OPENED 04/23/91 DATE CODE EV 10-79 SERIAL NUMBER A6814285 MODEL AND GRADE 700 30-06 BDL ORDER 91-09592
 ACCESSORIES SLING STRAP W/STUDS W/SWIVELS SOFT CASE SCOPE BASE

OM:

WELDON, H W
 10701 EDGEWATER RD
 FORT SMITH

AR 72903

SHIP TO:

WELDON, H W
 10701 EDGEWATER RD
 FORT SMITH

AR 72903

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

AIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

IN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

Repair - and letter of explanation
 explanation - claims firearm discharged on
 safe release twice

N FAULT

Sent to J. Stehl
 cannot duplicate complaint - rifle cannot be made to fire when safety is
 closed. However, disassembly of rifle revealed trigger assembly is shipping wet
 with oil. This condition coupled with cold temperatures could cause problems
 on left - 0.12"; trigger pull 4.4 pounds.

Offer to clean present assembly (if possible);
 if not, offer replacement trigger at
 normal cost, as gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/90