

November 30, 1989

Repair Department
Remington Arms Co.
Wilmington, Del. 19898

The attached notice reminded me that I have a rifle such as described. It is a Mod. 700 LH, cal. 270, Ser. no. 6628872. I do not use it often because I lack confidence in it's reliability.

On one occasion, it failed to fire upon release of the safety and pull of the trigger. After working the safety back & forth several times it fired without pulling the trigger.

At another time, it fired while loading another round into the chamber without touching the trigger.

On every occasion, it will not load the next to the last round from the magazine to the chamber.

May I have authorization to return the rifle for inspection & repair. If there is to be a charge, please advise as I would rather trade it than spend a lot of money on it.

W. E. Whipkey

W. E. Whipkey
Rt. 1, Box 50
Hallsville, Tx. 75650

R90-02848
17 year old gun

2 4

*Letter sent 11/3/90
Serial # put in screen 23 for attention KAC*