

Remington



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

May 31, 1989

Mr. Mark Yoder
Route 2, County RD 1100
Box 225
Nappanee, IN 46550

Dear Mr. Yoder:

Examination has been completed on the Model 700 ADL 22-250 Rem. caliber rifle, serial number B6844094, that you returned to us a short time ago, because ".....put the safety off and it misfired."

The returned firearm, which was produced in January of 1987, has been thoroughly examined and found to contain our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all necessary tests and inspections prior to being shipped from our facility.

The general condition of the gun appeared to be excellent and, in going over the individual parts, we found headspace, recoil shoulders and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction you reported. All tolerances and dimensions were found to be normal. Trigger pull was measured at 5-1/2 pounds, and the sear-lift with the safety in the "on-safe" position was well within our specifications at .015". The only manner in which the rifle could be made to fire was with the safety off and the trigger pulled, as designed.

Since we found the firearm to function properly in every respect, we are prepared to return it in its present condition. However, if you do desire, we will replace the trigger assembly with a new one