

Remington Arms Co., Inc.
Product Service
Legal Case #:2111

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
140734	1/25/2008	2/8/2008	2/8/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Roger	Franson	1215 East 4338 North	Buhl	ID	83316		H 208-543-6825 W 208-543-4777 E maryelo@yahoo.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI PD S fired on safe release C	Cause:4006 Altered Adjustments or Components Concern:1007 Fired on Safe Release		Unknown	

2/11/08-correspondence from repair-trigger would not pull, put safety on and took it off and then gun fired when safety was moved.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	7/7MM08 REM	24741	S7606971	AP	3/27/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	BUCKEYE SPORTS SUPPLY		Y			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Repace TA at discount						
	Repair/Replacement Cost	Repair/Replacement Date				

2/11/08-quote sent to replace ta at discount.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/8/2008
	Product Type		RF
	Action Type		A

	Assigned To	F.SUPRY
Cause	4006	Altered Adjustments or Components
Barrel	Description	20" 7MM08 REM
	Date Code	AP
	Bore Plugged	False
	Bulged	False
	Fired	False
	Fired while Obstructed	
Bolt	Muzzle/Crown Condition	Worn; Functioning
	Firing Pin	Slightly Worn; Functioning
	Shroud	Slightly Worn; Functioning
	Face	Slightly Worn; Functioning
	Handle	Worn; Functioning
Extractor	Stop	Slightly Worn; Functioning
	Condition	Slightly Worn; Functioning
	Cut Condition	Slightly Worn; Functioning
Locking	Ext/Eject Test	False
	Block Condition	---Select---
	Lug Condition	Slightly Worn; Functioning
Overall	Notch Condition	---Select---
	Exterior Condition	Slightly Worn; Functioning
	Stock Condition	Slightly Worn; Functioning
Receiver	Fore End Condition	---Select---
	Condition	Slightly Worn; Functioning
Safety	Bulged	False
	Description	STANDARD M/7 SAFETY
	Function	Like new; Functioning
Sear	Sub-Assembly	Non-ISS
	Lift	---Select---
	Notch	Like new; Functioning
Feeding Test	Tests	Test Fired
		False
Trigger		False
	Condition	Slightly Worn; Functioning
	Pull	---Select---
	Altered	True
	Sub-Assembly	Other Remington
		4#
		TRIG SET SCREWS ALTERED

RECEIVED
FEB 11 2008
BY: *[Signature]*

2111
January 16, 2008
AP 3/95
4#
20"
.012

To: Remington Repair Service

I got a first model 7, the blued one, for my wife and when she would not let me use it, I got one for myself, the stainless steel one.

They both worked real good until the season of 06. I was elk hunting at -20 degrees and found some elk bedded down. I took the safety off and pulled the trigger. It would not pull. I put the safety back on. When I took it off again, the gun fired. I tried the same procedure again. It fired again when I took the safety off. I did not think too much of it seeing it was 20 below. I just thought it was frozen up. That was the stainless steel one.

Then in 07 season, my grandson used my wife's blued one for deer hunting. We found a deer standing unaware of us. I told him to shoot it. He took the safety off and tried to shoot it, but could not pull the trigger. He put the safety back on and when he put it off again, the gun went off.

This time the temperature was 47 above. It scared me to have a gun go off for my grandson.

I have had many Remington rifles in my life. These were the first two to give me any troubles. Has there been any recalls or anything on the model sevens?

could not duplicate concern.
Trig. set screws altered.
replace TPA, check down, clean
at 1/2 normal changes.

Quote

Your help would be appreciated.

Thank you,

Roger Franson

Roger Franson
1215 East 4338 North
Buhl, Idaho 83316

Home phone: 208-543-6825

Work phone: 208-543-4777

Serial Number: S7606971

Model: 7



RE00140734

(NOTE: Please print and complete this form, and then include it with your firearm.)

BARBER - Kinzer PPS GAL RE0008513

INVOICE
10 50833

DATE _____

1-20-9

Customer Order No.

Project Contract No. _____

TC 4705 **KEEP THIS SLIP FOR REFERENCE**

TRAHO MOTOR FUEL TAX	Gallons	Rate .21	Amount
----------------------------	---------	-------------	--------

440

Dephume Meier Reading - Gak

ON 2105

Sale No.

Brodie or Smith Meter Reading - Gals

10th-

Delivered By

Payment Received By	Date
---------------------	------

Payment Will Be Made on or Before:

Buyer acknowledges receipt of goods and agrees to the terms set forth by the Seller and listed below for all purchases made within one year of this date. A late **Finance Charge** as computed by Seller's current Terms and Conditions (show below) may be assessed against all late payments.

1.750 % per month or an **Annual Rate** of 21 %

[illegible]
