

Remington Arms Co., Inc.  
Product Service  
Legal Case #:2850

## Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
154647	11/5/2008	11/6/2008	11/6/2008				

## Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Kell Brothers		Kell Brothers	4539 Rt 209	Elizabethville	PA	17023		W 717-362-3234

## Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S	Fired on bolt closing	Concern:1008 Fired on Bolt Closing		Unknown
C				

Customer says, discharge when closing bolt.

## Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/222 REM	20000	6267899	BT	1/1/1970
Date Purchased	Where Purchased	Accessories	Original Owner			
	ART COOK LAUREL MD	TWO PIECE SCOPE BASE	U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
------------	-------------------	--------------	---------------	-----------------	----------------	---------------

## BLM Program

Repair/Replacement Cost	Repair/Replacement Date
65.00	11/6/2008

Trigger screw settings altered, has very little trigger return, as received will follow-down as bolt is closed. Install new TA, clean action, and check over completely under the bolt lock modification program fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		11/6/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		24" 222 REM
	Date Code		BT
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	

Bolt	Face	Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	MARS/SCRATCHES
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.008
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

**Arms Services Repair & Estimate System**

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

**Repair Inquiry**

Repair Number: **RE00154647** Serial: 6267899 Model: 700 Center Fire Caliber: 222 REM Produced: 03/13/1970 Repairman: Status: New 11/5/2008 8:36:01 AM

Verify Repair

**Address Information**

Customer: Received From Return To: Received From

Name: **KELL BROTHERS**

Address 1: **4539 RT 209** Address 2: **PO Box**

City: **ELIZABETHVILLE** State: **PA** Zip Code: **17023** Country: **US**

FFL: **8 23 043 01 98 58693 022009**

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	User ID	Desc1	Desc2	Current Status
11/5/2008 8:27:1	valentds	Repair Added		New
11/5/2008 8:35:2	valentds	Repair information change		11/5/2008 8:36:01 AM
11/5/2008 8:36:0	valentds	Repair information change		valentds
11/5/2008 8:36:3	valentds	From: Check In	To:	Product Services
11/6/2008 9:51:4	supryll	Returned for repair	Bolt Lock Modification Program	Repair Location
				ILN
				Current Location
				ILN
				Transfer Number

Repair Search Refresh Close

View R

supryll 11/6/2008 9:52 AM CAPS NUM INS SCRL

start Inbox - Microsoft Out Arms Services Repair Microsoft Excel - PS H Current Cases - Micro 9:52 AM

Altered adjustments

Bolt Lock Modification Program

IST 1/70  
24"  
~~24~~  
:008

## Factory Repair Instructions

Model Number:					
Serial Number:					
Are you the original owner?					
Name:					
Date of Purchase:					
Address (no PO Boxes):					
City:					
State:					
Zip:					
Phone (Daytime):					
Fax:					
E-mail Address:					
I would like to receive future e-mail updates from Remington.					
Please describe your problem:					
Ammunition Information:					
Manufacturer:					
Type:					
Other (i.e. bullet weight/type, shot size, powder):					
Handload Information:					
Powder Used:					
Powder Weight:					
Case/Hull Used:					
Primer Used:					
Bullet Type/Shot Size:					
Reloader Used:					
Firearms Care (Cleaning and Lubrication):					
Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds)					
How often do you clean the action? (Months or Number of rounds)					
Number of rounds)					

Serial Number:

6267899

Model: 700



RE00154647

Number of rounds)

TRIG. SET SCREENS ALTERED, HAS  
MIX TRIG RETURN, WILL FOLLOW DOWN  
REPLACE TPA, check over check  
under bolt lock program for  
\$ 20.00 + SKH.