

Remington Arms Co., Inc.
Product Service
Legal Case #:2737

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
151928	9/30/2008	10/1/2008	10/1/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Jeff	Labelle	27261 259th St	Holcombe	WI	54745		H 715-595-6419 F 612-677-3853 E jeff@labelle.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern			
S	fired on safe release Concern:1007 Fired on Safe Release		Unknown	
C				

10/3/08-correspondence from repair-gun has fired on safe release on multiple occasions. Please modify the bolt lock mechanism and repair or replace the trigger assembly.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR		6798569	EY	10/1/1974
Date Purchased	Where Purchased	Accessories	Original Owner			
		TWO PIECE SCOPE BASE	U			

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
BLM Program						
	Repair/Replacement Cost	Repair/Replacement Date				

10/1/2008 Returned to AS for bolt lock modification program fls.

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		10/1/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		EY
	Bore Plugged	False	
	Bulged	False	

	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	--Select--	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	--Select--	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	--Select--	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.011
	Notch	Like new; Functioning	
Feeding Test	Tests	Test Fired	False
		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	6#
	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Arms Services Repair & Estimate System

FileAdd RepairEstimate RepairExpedite RepairInquiryRepair ToolsCSR ToolsReportsTable MaintenanceSystem MaintenanceHelp

Repair Inquiry

Repair NumberRE00151928

Verify Repair

Serial: 6798569 Model: 700 Center Fire Caliber: 3006 SPRG

RepairmanRobert Frink

StatusApproval Hold 10/1/2008 8:38:02 AM

Address Information

Customer:Received FromReturn ToReceived From

NameJEFF LABELLEJEFF LABELLE

Address 127261 259TH STREET27261 259TH STREET

Address 2PO BoxPO Box

CityHOLCOMEHOLCOME

StateWIViZip Code5474554745CountryUSUS

FFL

Contact / ConditionProblemsEstimateHistory / StatusShipping / Billing

Date	Code	User ID	Desc1
9/26/2008 5:29:1	New	VALENTOS	Repair Added
9/30/2008 12:34:	Expedite	pencerl	From: Check In
9/30/2008 2:53:4	Estimate	frinkie	Estimate Update
10/1/2008 8:29:2	Maint	Travisbw	Repair Maintenance
10/1/2008 8:38:0	Estimate	frinkie	Estimate Update
10/1/2008 9:38:2	Expedite	pencerl	From: Repair Bench

☐ Shipping Hold

☐ InterFace Hold

☐ Estimate Sent

☐ Parts Received

☐ Passed Inspection

☐ Return As Received

☐ Has been Approved

☐ Internal Repair

Current Status

Approval Hold10/1/2008 8:38:02 AM

Inlinkie

Approve Rack

Repair LocationILEN

Current LocationILEN

Transfer Number

Repair Search

Refresh

Close

supryll10/1/200810:35 AMCAPSNUMINSERCL

startInbox - Microsoft Out...Arms Services RepairP5 Hold Guns A510:35 AM



General Repair Form

Back to Repair Services

NOTE: Please complete and print this form, and then include it with your firearm

Model Number: <u>M700 / 30-06</u>	Serial Number: <u>6798569</u>
Name: <u>JEFF LABELLE</u>	Date of Purchase: <u>ABOUT 1970</u>
Address (no PO Boxes): <u>27261 259th ST.</u>	
City: <u>HOLCOMBE</u>	State: <u>WI</u> Zip: <u>54745</u>
Phone (Daytime): <u>715-595-6419</u>	Fax: <u>612-677-3853</u>
E-mail Address: <u>jeff@labelle.com</u>	
Please describe your problem:	
<p>I BOUGHT THIS GUN NEW MORE THAN 35 YEARS AGO. THIS GUN HAS FIRED ON SAFETY RELEASE ON MULTIPLE OCCASIONS. PLEASE MODIFY THE BOLT LOCK MECHANISM AND REPAIR OR REPLACE THE TRIGGER ASSEMBLY.</p>	
<p>500 characters left</p> <p>THANK YOU!</p>	
NOTE: Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.	
<p>⚠ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p>	
<p>Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p>	

©2008 Remington Arms Company, Inc. All Rights Reserved.
 Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Websites

Other Sites



Serial Number: **6798569**

Model **700**



RE00151928

could not duplicate concern.
 Trg. Assm very dirty.
 Replace TPA, check over,
 clean under bolt lock
 program Ron \$ 20.00

Quote