

Remington Arms Co., Inc.
Product Service
Legal Case #:2361

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 144847 | 4/24/2008 | 4/25/2008 | 4/25/2008 | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|----------|------------|---------------|---------------------|--------------|-------|-------|-----|--|
| Reporter | | Joseph | Leon-Guerrero | 4915 Sherlyn Ave SE | Port Orchard | WA | 98367 | | H 360-876-0591 E ursula@leon-guerrero.com |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|--|-------------|-------------------|----------------|
| PI | | | | |
| PD | Cause:4015 Improper Maintenance | | Unknown | |
| S | fires on safe release Concern:1007 Fired on Safe Release | | | |
| C | | | | |

4/29/08-correspondence from repair-firearm would sometimes accidentally fire while moving the safety from safe to fire. lw

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|---------------------------|----------------------|----------------|----------|------|----------|
| Remington | CF/BA | 700/7MM RM | 20000 | B6603856 | OE | 7/1/1984 |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | SOUTHERN GUN OPA-LOCKA FL | TWO PIECE SCOPE BASE | Y | | | |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|------------------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Replace TA at discount | | | | | | |
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |

4/29/08-quote sent to replace ta at discount.lw

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|-------------|--------------|------|-----------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 4/25/2008 |
| | Product Type | | RF |
| | Action Type | | A |

| | | |
|--------------------------|------------------------|--------------------------------|
| | Assigned To | F.SUPRY |
| Cause | 4015 | Improper Maintenance |
| Barrel | Description | 24" 7MM RM |
| | Date Code | OE |
| | Bore Plugged | False |
| | Bulged | False |
| | Fired | False |
| | Fired while Obstructed | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning |
| Bolt | Firing Pin | Slightly Worn; Functioning |
| | Shroud | Slightly Worn; Functioning |
| | Face | Slightly Worn; Functioning |
| | Handle | Slightly Worn; Functioning |
| | Stop | Slightly Worn; Functioning |
| Extractor | Condition | Slightly Worn; Functioning |
| | Cut Condition | Slightly Worn; Functioning |
| | Ext/Eject Test | False |
| Locking | Block Condition | ---Select--- |
| | Lug Condition | Slightly Worn; Functioning |
| | Notch Condition | ---Select--- |
| Overall | Exterior Condition | Slightly Worn; Functioning |
| | Stock Condition | Slightly Worn; Functioning |
| | Fore End Condition | ---Select--- |
| Receiver | Condition | Slightly Worn; Functioning |
| | Bulged | False |
| Safety | Description | STANDARD M/700 SAFETY |
| | Function | Slightly Worn; Functioning |
| | Sub-Assembly | Non-ISS |
| Sear | Lift | ---Select--- |
| | Notch | Like new; Functioning |
| | Tests | Test Fired |
| Feeding Test | False | False |
| Trigger | Condition | Slightly Worn; Not Functioning |
| | Pull | ---Select--- |
| | Altered | False |
| | Sub-Assembly | M/700 Non-Bolt Lock |
| Non-Remington Components | Description | TWO PIECE SCOPE BASE |

Arms Services Repair & Estimate System

File

Add Repair

Estimate Repair

Expedite Repair

Inquiry

Repair Tools

CSR Tools

Reports

Table Maintenance

System Maintenance

Help

Repair Inquiry

Repair Number

RE00144847

Serial: 86603856 Model 700 Center Fire Caliber 7MM REM MAG Produced: 07/23/1984

Repairman

Status

Repairing 4/25/2008 10:42:36 AM

Verify Repair

Address Information

Customer:

☒ Received From

Return To:

☐ Received From

Name

JOSEPH LEON-GUERRERO

JOSEPH LEON-GUERRERO

Address 1

4915 SHERLYN AVENUE SE

4915 SHERLYN AVENUE SE

Address 2

PO Box:

PO Box:

City

PORT ORCHARD

PORT ORCHARD

State

WA

Zip Code:

99367

Country:

US

State

WA

Zip Code:

99367

Country:

US

FFL

Contact / Condition

Problems

Estimate

History / Status

Shipping / Billing

| Date | Code | User ID | Desc1 |
|------------------|----------|----------|------------------------|
| 4/24/2008 11:51 | New | valentds | Repair Added |
| 4/24/2008 11:52 | Expedite | valentds | From: Check In |
| 4/25/2008 8:58:0 | Closed | pencarl | |
| 4/25/2008 10:42 | ReOpened | pencarl | |
| 4/25/2008 10:42 | Expedite | pencarl | From: Product Services |

☐ Shipping Hold

☐ InterFace Hold

☐ Estimate Sent

☐ Parts Received

☐ Passed Inspection

☐ Return As Received

☐ Has been Approved

☐ Internal Repair

Current Status

Repairing

4/25/2008 10:42:36 AM

pencarl

Repair Bench

Repair Location

ILN:

Current Location

ILN:

Transfer Number

Repair Search

Refresh

Close

supvrl

4/25/2008

2:07 PM

CAPS

NUM

INS

ISRL

start

Inbox - Microsoft Outlook

Arms Services Repair

2:07 PM

April 19, 2008

Remington Arms Co.
14 Hoefler Avenue
Ilion, NY 13357

RE: 7mm Magnum
Model #700
Serial #B6603856

To Whom It May Concern:

In 1984, I purchased this rifle. When in lock and load and not touching the trigger, this firearm would sometimes accidentally fire while moving the safety switch from "S" position the "F" position. Because of this, I have not fired the rifle more than 50 rounds.

I understand there may be a recall on this model. If so, please repair/replace as necessary. If there is no recall, I would like to have my rifle repaired. Please contact me as to the cost and I can give you billing information.

Please contact me with any questions or further information at 360.876.0591 or ursula@leon-guerrero.com

Thank you for your help.

Sincerely,

Joseph Leon Guerrero

Joseph Leon-Guerrero
4915 Sherlyn Avenue SE
Port Orchard, WA 98367

Serial Number: **B6603856**

Model: **700**



RE00144847

TRIGGER ASSM DIRTY, TRIGGER & TRIGGER
PIN RUSTED & BINDING.
REPLACE TRA, check owner
clean at 1/2 normal charge

Quote