

Remington Arms Co., Inc.
Product Service
Legal Case #:3442

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
166906	4/24/2009	4/27/2009	4/27/2009				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Atomic City Weapons	John	Mitchell	363 Ridgecrest Ave	Los Alamos	NM	87544		H 505-672-4122 W 505-665-9260 C 505-231-1991 E jxm@lanl.gov

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S	fired while unloading	Concern:1020	Fired on Bolt Opening	Unknown
C				

5/1/09 Per letter with rifle, Mitchell is returning the rifle for a customer/friend. The rifle accidentally fired within the house while unloading, is it unclera whether the safety was engaged. The owner is positive he did not pull trigger. Owner and family are not comfortable with the rifle until rifle has been repaired by a Remington gunsmith. The rifle has had very little use and action has not been out of the stock or any repairs/modifications made.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPR	20000	B6471955	PD	6/1/1983
Date Purchased	Where Purchased	Accessories	Original Owner			
	MAURICE SPTG GD CHICAGO IL	SCOPE BASE,HARD CASE	U			

CONCERN:ACCIDENTAL DISCHARGE

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
repair at 1/2 normal charges as goodwill gesture						
	Repair/Replacement Cost	Repair/Replacement Date				
	62.39	5/1/2009				

5/1/09 Could not duplicate concern. Trig assm very dirty & sticky. Sear works sluggish. Replace trig assm, check over, clean at 1/2 normal charges.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/27/2009
	Product Type		RF
	Action Type		A

	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPR
	Date Code		PD
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.011
	Notch	Slightly Worn; Functioning	SLUGGISH
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	ASSM VERY DIRTY/STICKY SEAR SLUGGISH
	Pull	---Select---	4.5#
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		SCOPE BASE,HARD CASE

Arms Services Repair & Estimate System

File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Maintenance System Maintenance Help

Repair Inquiry

Repair Number: **RE00166906** Serial: 86471956 Model: 700 Center Fire Caliber 3006 SPRG Produced: 06/10/1983 Repairman: Bruce Travis Status: ApprovalHold 4/27/2009 6:01:09 AM

Verify Repair

Address Information

Customer: **JOHN MITCHELL** Received From: **JOHN MITCHELL** Return To: **JOHN MITCHELL** Received From:

Address 1: **363 RIDGECREST AVE** Address 2: **363 RIDGECREST AVE** PO Box: **PO Box**

City: **LOS ALAMOS** City: **LOS ALAMOS** PO Box: **PO Box**

State: **NM** Zip Code: **87544** Country: **US** State: **NM** Zip Code: **87544** Country: **US**

FFL: **5 85 028 01 1G 34294 072011**

Contact / Condition	Problems	Estimate	History / Status	Shipping / Billing
Date	Code	User ID	Desc1	Desc2
4/24/2009 8:03:0	New	valentds	Repair Added	
4/24/2009 8:06:5	Update	valentds	Repair information changed	
4/27/2009 5:59:4	Expedite	Travisbw	From: Check In To: Repair Bench	
4/27/2009 6:01:1	Estimate	Travisbw	Estimate Update Status: ApprovalHold	
4/27/2009 6:21:3	Expedite	pencil	From: Repair Bench To: ApproveRack	

Shipping Hold InterFace Hold Estimate Sent Parts Received Passed Inspection Return As Received Has been Approved Internal Repair

Current Status: ApprovalHold 4/27/2009 6:01:09 AM Travisbw ApproveRack Repair Location ILN Current Location ILN Transfer Number

Repair Search Refresh Close

suprjll 4/27/2009 8:43 AM CAPS NUM JNS SBEL

star Inbox - Microsoft Out... Arms Services Repair Part Search by Materi... 8:43 AM

27.00
 35.39

 62.39

RECEIVED
 APR 28 2009
 BY:

3442

22"
906/83
4.5"
011

TO: Remington Service

FROM:

John Mitchell
Atomic City Weapons
363 Ridgecrest Ave
Los Alamos, NM 87544

Subj; **Accidental Discharge?**
Remington 700ADL 3006
S/N **B6471955**

I am returning this firearm for inspection and or repair for a customer/friend. This rifle was accidentally fired within the confines of a house while unloading; it is unclear whether the safety was engaged the owner is positive he did not pull trigger. The owner and family are not comfortable with this rifle nor are they willing hunt with sell or trade until this rifle has been repaired by a Remington gunsmith. This rifle has had very little use and action has not ever been out of the stock i.e. no repairs or modifications have ever been made to this rifle.

Thank you very much

FFL# 5-85-028-01-1G-34294

John Mitchell
Atomic City Weapons
363 Ridgecrest Ave
Los Alamos, NM 87544

505-665-9260 day
505-672-4122 eve
505-231-1991 cell eve

jxm@lanl.gov
jxmitchell@msn.com

Serial Number: **B6471955**

Model: **700**



RE00166906

could not duplicate concern.
TRIG. ASSM very dirty + STICKY.
SEAR WORKS sluggish. replace
TRIG. ASSM, check over, clean
at 1/2 normal charges.

Quote