

Remington Arms Co., Inc.
Product Service
Legal Case #:2411

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
146375	6/13/2008	5/19/2008	6/16/2008				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter		Wilburn	Umstatt	5 Arrington Ave	Maysville	KY	41056		H 606-564-5019

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI shot through PD mattress & boxspring S fired on bolt closing C	Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing		Unknown	

5/19/08-Customer purchased rifle used at a gun show. On two occasions, it fired when the bolt was closed. Once at the gun range and once at home, shooting a hole through his mattress & boxspring. He would like to send it in to be evaluated.lw

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22 250 REM	27488	E6205162	XP	12/18/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	NATIONAL RECREATIONAL SHOOTING SUPP	TWO PIECE SCOPE BASE, RINGS	N			

5/19/08-purchased used at a gun show.lw CONCERN:FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
------------	-------------------	--------------	---------------	-----------------	----------------	---------------

Consumer

paid for
repairsRepair/Replacement Repair/Replacement
Cost Date

5/20/08-sending box, ars, ltr.lw 6/19/08 the consumer authorized and paid for repair of this firearm. cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		6/16/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 22 250 REM HB
	Date Code		XP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
	Condition	Slightly Worn; Functioning	

Receiver	Bulged	False	
Safety	Description		STANDARD M/700 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	---Select---	.016
	Notch	Like new; Functioning	
		Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	
	Pull	---Select---	2.5#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	

Remington®2411
May 20, 2008XP 12/95
25#
26"
016

Wilburn Umstatt
5 Arrington Ave
Maysville, KY 41056-1701

Number: **E6205162**Model: **700****RE00146375**

Subject: Model 700
RE: Case #2411

Dear Mr. Umstatt,

We were sorry to learn about the unfortunate incident you experienced with your Model 700. As I understand it, the rifle fired when you closed the bolt. We are certainly glad that no one was injured, and that you are anxious to get back to enjoying the shooting sports.

As we discussed, I have enclosed a prepaid UPS shipping label for you to ship the firearm back to our factory for examination. I have also included a copy of this letter to put inside the shipping box. (The box will come under separate cover). The letter inside is important as we want to be sure the firearm is logged in correctly. On the factory repair form, please provide additional information about the incident, including the date of the last occurrence, type of weather, type of ammunition being used, etc.

We apologize for the inconvenience that this incident has caused and we hope that our actions will keep you as a loyal Remington customer.

Sincerely,

Laura Watson
Consumer Affairs Administrator
Remington Arms Company

Phone: 800-243-9700 ext 8789
Fax: 336-548-7890
E-mail: laura.watson@remington.com

TRIG. ASSM. SET SCREWS ALTERED,
WILL FOLLOW DOWN. REPLACE
TPA, CHECK OVER, CLEAN AT
1/2 NON WAT CHARGES.

Quote

Repairing at special price

Remington

Factory Repair Instructions

(NOTE: Please print and complete this form, and then include it with your firearm.)

Model Number: 700 BDL

Serial Number: E670 5162

Are you the original owner?: ☐ YES ☒ NO

Name: WILBUIN UMSTATT

Date of Purchase: 2000

Address (no PO Boxes): 5 ARIZINGTON AVE

City: MAYSVILLE

State: KY

Zip: 41056

Phone (Daytime): 606-564-5019

Fax: NONE

E-mail Address: NONE

☒ I would like to receive future e-mail updates from Remington.

Please describe your problem: FIRES ON CLOSING BOLT

Ammunition Information:

Manufacturer:

Type:

Other (i.e. bullet weight/type, shot size, powder):

Handload Information:

Powder Used: IMR 4064

Powder Weight: ~~55 gr~~ 35.5 gr

Case/Hull Used: REM - WIN

Primer Used: CCI Horn Small Rifle

Bullet Type/Shot Size: 55 gr. SP

Reloader Used: LYMAN

Firearms Care (Cleaning and Lubrication):

Brand of cleaning solution used: REM-OIL + HOPPES

How often do you clean the bore? (Months or Number of rounds) AFTER SHOOTING

How often do you clean the action? (Months or Number of rounds) 6 mo

How often do you clean the trigger assembly? (Months or Number of rounds)

Brand of lubricant used: REM-OIL - HOPPES

How often do you lubricate the bore? (Months or Number of rounds)	AFTER SHOOTING
How often do you lubricate the action? (Months or Number of rounds)	6 mo
How often do you lubricate the trigger assembly? (Months or Number of rounds)	6 mo
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	
Comments:	
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	
What were the services performed?	
Ship your INSURED firearm by either UPS or Parcel Post to:	
REMINGTON ARMS CO., INC ATTN: Arms Service Division 14 Hoefler Ave Ilion, NY 13357	
<p>WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.</p> <p>:: Record the serial number of your firearm before sending it.</p> <p>:: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.)</p> <p>:: Remove all accessories from your firearm to prevent loss or damage.</p> <p>:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.</p> <p>:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.</p> <p>Charge repairs will be processed using the following guidelines:</p> <p>:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)</p> <p>:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.</p>	



May 20, 2008

Wilburn Umstatt
5 Arrington Ave
Maysville, KY 41056-1701

Subject: Model 700
RE: Case #2411

Dear Mr. Umstatt,

We were sorry to learn about the unfortunate incident you experienced with your Model 700. As I understand it, the rifle fired when you closed the bolt. We are certainly glad that no one was injured, and that you are anxious to get back to enjoying the shooting sports.

As we discussed, I have enclosed a prepaid UPS shipping label for you to ship the firearm back to our factory for examination. I have also included a copy of this letter to put inside the shipping box. (The box will come under separate cover). The letter inside is important as we want to be sure the firearm is logged in correctly. On the factory repair form, please provide additional information about the incident, including the date of the last occurrence, type of weather, type of ammunition being used, etc.

We apologize for the inconvenience that this incident has caused and we hope that our actions will keep you as a loyal Remington customer.

Sincerely,

A handwritten signature in black ink that reads "Laura Watson". The signature is fluid and cursive.

Laura Watson
Consumer Affairs Administrator
Remington Arms Company

Phone: 800-243-9700 ext 8789
Fax: 336-548-7890
E-mail: laura.watson@remington.com

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025
Phone 800-243-9700 • www.remington.com

Oakley, Anita B.

From: Watson, Laura M.
Sent: Monday, May 19, 2008 2:35 PM
To: Oakley, Anita B.
Subject: If this doesn't work, I'll bring it over :)
Attachments: image001.jpg



www.remington.com

Remington Arms Company, Inc.
 870 Remington Drive
 P. O. Box 700
 Madison, NC 27025-0700

ARS LABEL REQUEST

DATE:	5/19/2008	REQUESTED BY:	Laura Watson
QUANTITY:	1	WEIGHT PER PACKAGE:	12
PLEASE CHECK ONE:			
MEDIA			
COORDINATOR			
TO MAIL		I WILL MAIL XXXX	
DESCRIPTION: REF: 700			

LABEL INFORMATION

MAIL LABEL TO: Wilburn Umstattd		4XX596 MAY 19, 2008 ALL CURR USD 1 OF 1	
5 Arrington Ave		SERVICE GND COM ACT WT 12.0 LBS	
Maysville, KY 41056		TRACKING# 1Z4XX5969067670494	
		REF 1: WILBURN UMSTATTD/LW	
		REF 2: REF# 700	
		HANDLING CHARGE 0.00	
		SINGLE-PIECE PUB RATE CHRG:	
RETURN ITEM	Ilion, NY	DV 0.00	COD 0.00
	Attn: Product Service	DC 0.00	DG 0.00
	Factory Only	AH 0.00	PR 0.00
		TOT PUB CHG 7.73	PUB+HANDLING 7.73
	(Need a label please)		

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

5/19/2008