Remington Arms Co., Inc. **Product Service** Legal Case #:2112

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete

140693 1/25/2008 2/8/2008 2/8/2008

Customer Information

Business First Name Last Name Street City State Zip Age Contact Type

724 CR 44850 Blossom TX 75416 W 903-982-5294 Reporter Lock Stock N Barrel Lock Stock N Ba

Incident Information

Codes Repair Est. Medical Treatment Medical Status Claims

PΙ

Could Not Duplicate Concern PD Cause:4038

Unknown

Concern:1007 Fired on Safe Release S fired on safe release

C

2/11/08-correspondence from repair-rifle has discharged 2 x when safety was pushed forward. Dealer tried to increase sear engagement and pull wt.lw

Firearm Information

Model/Ga. SKU Serial Bbl. **DOM** Mfg. Type CF/BA 710/300 WIN MA 27414 71295426 CA 4/17/2006 11:13:40 AM Remington

Date Purchased Where Purchased Accessories **Original Owner**

5/1/2007 SPORTS SOUTH INC **SCOPE BASE**

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Replace TA at

n/c

Repair/Replacement Repair/Replacement

> Cost Date 35.00 2/11/2008

2/11/08-replace TA at n/c to restore faith in rifle.lw

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/8/2008
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=2112&Type=Case

2/11/2008

Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 300 WIN MAG
	Date Code		CA
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/710 SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
Sear	Lift	Select	N/A
	Notch	Like new; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	Select	5#
	Altered	False	
	Sub-Assembly	Other Remington	

BARBER - Kinzer PPS GAL RE0009308 File Add Repair Estimate Repair Expedite Repair Inquiry Repair Tools CSR Tools Reports Table Mantenance System Maintenance Help Serial: 71295426; Model 710; Center Fire (Caliber, 300 WIN:MAG Produced: 04/17/2006; Repail Number RE00140693 Status New 1/25/2008 7:29:01 AM Verify Repair Address Information Return To: Name: LOCK STOCK N BARREL LOCK STOCK N BARREL Address 1: ATTN MICHAEL WRIGHT ATTN MICHAEL WRIGHT Address 2: 724 CR 44850 City: BLOSSOM 724 CR 44850 PO Box PO Box: BLOSSOM State: TX Zip Code: 75416 Countiy: US State TX Zip Code 75416 Country US History / Status Shipping / Billing = Current Stalus
 Date
 Code
 UserID

 1/25/2008/7:29 (Image: New point of the control of the contro Desc1 🦵 Shipping Hold Repair Added InterFace Hold 1725/2008 7:29:01 AM 2/8/2008 8:17:13 Expedite From: Check In "⊌valentds ☐ Estimate Sent. aRepair Bench. Parts Received Repair Location Passed Inspection ILN Réturn As Received Current Location S. ILN ☐ Has been Approved Transfer Number ☐ Internal Repair Repair Search <u>R</u>efresh Close 2/8/2008 11.27 AM NUM 3 Ontox: Microsoft Onto 19 1251: 10 General Control of Ameson vices Repair (20 Information 20 Information Vice of Control o

	How often do you lubricate the trigger assembly? (Months or Number of rounds)		
	Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?		
,	nen was the last time that your firearm was serviced by a Remington authorized pairman/gunsmith?)		
What were the services performed?)			
	NOTE: In order to better service our customers some firearms/parts are sent to a certified Remington Premier Authorized Repair Center.		
	Ship your ENSURED firearm by either UPS or Parcel Post to:		
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357			
	Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage. Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused. Ship your ENSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.		
	Charge repairs will be processed using the following guidelines:		
	:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)		
	:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express; Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.		

©2008 Remington Arms Company, Inc. All Rights Reserved.

Investor Relations | Other Remington Brand Products | Legal Notices | About Us

Visit Our Other Remington Websites
Other Sites

Remington.



could not duplicate concer replace TPA, check over, clear AT N/c. to Mestone confidence in Rifle.