BARBER - Kinzer PPS GAL RE 0009646

Remington Arms Co., Inc. **Product Service**

Legal Case #:5432

Case Information

RE# **Date Opened** 218857 1/14/2011

Date Opened(PS) 12/15/2010

Date Closed 1/17/2011

Incident Date

Pre Lit Lit Obsolete

Customer Information

Business First Name Last Name

Street

State Zip Age

Contact

Incident

Eric

Akerlind

2021 Leafwood Ln. Arcadia CA 91007

H 626-446-2219 E erqlo@dslextreme.com

Incident Information

Claims

Codes

PΙ

Repair Est. Medical Treatment Medical Status

PD

S

Altered Adjustments or Components Cause:4006 Concern: 1007 Fired on Safe Release

Unknown

C FSR

Customer called in. Stated that he is a target shooter and a couple of months ago he had a FSR. No damage, No injury. df

Firearm Information

Mfg. Remington Type

Model/Ga. 700/223 REM

SKU 27491

Serial Bbl. G6298361 LX

DOM

2/5/2003 6:27:27 PM

Date Purchased

CF/BA Where Purchased

Accessories

Original

Owner

ACUSPORT (MT) CORPORATION

TWO PIECE **BASE**

Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Release of Claims

Release Date

Reimbursement

Cash Settlement Date APV

Reim.

Cash Date APV

Per Ilion - Quote to repair

Settlement

Repair/Replacement Cost

Repair/Replacement Date

12/15/10: Sending ARS, ltr, form. df 1/21/11: Per Ilion - Will follow down. TA set screws altered & dirty. Replace TA, clean & test fire @ 1/2 normal charges - quote. Emailed quote to customer. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		1/17/2011	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		T.NAGLE	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5432&Type=Case

1/21/2011

BARBER - Kinzer PPS GAL RE 0009647

Cause	4006	Altered Adjustments or Components	
Barrel	Description		26" 223 REM HB
	Date Code	Ī	LX
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while]	
	Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
_	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
D	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.014
Sear	Notch	Slightly Worn; Functioning	
	Tasta	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN TRIG WILL NOT RETURN PROPERLY
	Pull	Select	1#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

26" LX2/03 LX2/03

CON

5432

December 15, 2010

Eric Akerlind 2021 Leafwood Ln. Arcadia, CA 91007 Ph: 626-446-2219

Ref: #5432

Dear Mr. Akerlind,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

Fax: 336-548-7872

AN 1 9 2011

BY

enclosure

G6298361 Model: 700

RE00218857

WILL FOLLOW JOWN. T.A. Set SCIEWS Altered & Dirty. Replace TPA, CLEAN LTS ST CIRC AT 1/2 NORMAL COST.

Quole

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

(Print	Reset				
Model 700 Number:	Serial				
Number: Number: G 629361 Are you the original owner?: XYES □ NO					
Are you the original own	Date of Purchase:				
Name: Eric Aterlind	Several years cop?				
Address (no PO Boxes):					
City: Arcadia	State: CA Zip: C1607				
Phone (Daytime): 636 446-2219	Fax:				
E-mail Address:(if e-mail address is provid					
be sent) erg of OSL	extreme 100m				
E-mail Address: Vision E-mail Address E-mail updates E-mail updat					
Please describe your problem and date of occurrence:					
occasionally when starting to shoot					
I chamber a round. IR the Softeter					
15 or. I take it off. whom doing					
this sometimes the woopen will live					
Ringer not on trigger characters left					
Ammunition Information:					
Manufacturer: Type:					
Other (i.e. bullet weight/type, shot size, powder):					
Handload Information:					
Powder Used: Ourget	Powder Weight: 25.9				
Case/Hull Used: Remarks Town Primer Used: Tester of					
Bullet Type/Shot Size: Siewa match Reloader Used:					
SIgr					
Firearms Care (Cleaning and Lubrication):					

Brand of cleaning solution used:				
How often do you clean the bore? (Months or Number of rounds)				
How often do you clean the action? (Months or Number of rounds)				
How often do you clean the trigger assembly? (Months or Number of rounds)				
Brand of lubricant used:				
How often do you lubricate the bore (Months or Number of rounds) every time I shoot				
How often do you lubricate the action? (Months or Number of rounds)				
How often do you lubricate the trigger assembly? (Months or Number of rounds)				
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > YES INO				
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)				
What were the services performed?)				
Ship your INSURED firearm by either UPS or Parcel Post to:				
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357				
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.				
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper				

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		12/15/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PKG:	10 lbs
PLEASE/CHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5432 rifle			

LABEL INFORMATION

MAIL LABEL TO: Eric Akerlind 2021 Leafwood Ln. Arcadia, CA 91007 Ph: 626-446-2219 RETURN ITEM TC Remington Arms Attn: Product Service Ilion, NY

APLEASE COMPLETE AND PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 DEC 15, 2010 ALL CURR USD SVC GNDCOM ACT UT 10.0 LBS
TRACKING# 1Z4XX5969067237382
REF 1:ERIC AKERLIND/CD/DMF 1 OF 1 REF 2:5432/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD COD 0.00 DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 11.74 RS 0.50 DGD 0.00 SD 0.00 0.00 SP 0.00 PR

PUB+HANDLING







