Remington Arms Co., Inc. Product Service Legal Case #:5015

Inform	

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 214945 12/16/2010 11/8/2010 12/17/2010 11/6/2010 Х

Customer Information

Business First Name Last Name Street City State Zip Contact Type Age H 336-325-2401 176 Butner Rd. 27043 C 336-409-7194 Incident Jimmy Baker Pinnacle NC F 336-325-2726

Incident Information

Claims Codes Repair Est. **Medical Treatment** Medical Status

ΡI

PD Cause:4013 Broken or Missing Parts S Concern:1007 Fired on Safe Release

Unknown

C FSR

11/8/10: Customer called in. He stated that he had a FSR. No damage - No injury. Wants rifle repaired. df

Firearm Information

Model/Ga. SKU Serial Bbl. DOM Mfg. Type 700ML/50 CAL 27588 ML233211 DU 9/29/2000 4:51:36 PM Remington ML/BA Date Purchased Where Purchased Accessories **Original Owner** AFT MKT FIRING PIN AND NIPPLE BANGERS LP

11/5/2000

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700ML/ML/BA

Cash Reim. Date Cash Date Release of Claims Settlement Release Date Reimbursement Settlement APV APV

Per Ilion - Repair @

n/c

Repair/Replacement Repair/Replacement Cost Date \$35.23 12/28/2010

11/8/10: Sending ARS, Itr, form & box. Box order# 1157125. df 12/28/10: Per Ilion - Connector is broken, safety parts missing. Replace TA & clean @ n/c. df

Examination[Remington/ML/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/17/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To]	T.NAGLE
Cause	4013	Broken or Missing Parts	
	Description		23" 50 CAL SS
	Date Code		DU
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Fired while Obstructed	<u> </u>	¬

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5015&Type=Case

12/28/2010

	Muzzle/Crown Condition	Slightly Worn; Functioning	·
	Firing Pin	Select	AFT MKT
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Select	
	Handle	Slightly Worn; Functioning	
	Stop	Select	7
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Not Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
Trigger	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN SOME SAFETY PARTS MISSING
	Pull	Select	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		AFT MKT FIRING PIN AND NIPPLE

23"

5015

November 8, 2010

CC

Jimmy Baker 176 Butner Rd. Pinnacle, NC 27043 Ph: 336-325-2401

Ref: #5015

Dear Mr. Baker,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

DEC 2 2 2010 BY:

enclosure

ML233211

Model: 700ML

RE00214945

connector is Broken, salety parts missing. Replace TOA + clear at N/C

#230145

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com Factory Repair Form

Print	Reset		
Model Number: 700 ML	Serial Number: ML 233211		
Are you the original ow	ner?: 🗹 YES 🗆 N	10	
Name: Jimmy Gray Baker	Date of Purchase:		
Address (no 176 Butner Road			
City: Pinnacle	State: N(.	Zip: 27043	
Phone (Daytime): 3%-325-24৬ (লো-স33646 794	Lav. /// 25 (17)/		
E-mail Address:(if e-mail address is provid be sent)	ed, notification of rece	ipt and shipment will	
E-mail A ☐ I would like to receive future e		emington.	
Please describe your problem and date of occurrence: Every time the SAFtey was pushed to the Firing A Position the gan would Fire without pulling the			
Took trigger out to old it also and had small part full out which I have enclosed small plastic			
Zipiec beg			
CONTRACTOR STATE	racters left		
Ammunition Information:			
Manufacturer:	Type:		
Other (i.e. bullet wei	ght/type, shot size,		

Handload Info	ormation:
Powder Used: Hodgen Tripla Se 7en	Powder Weight: 100 grains
Case/Hull Used:	Primer Used: Reming Kill
Bullet Type/Shot Size: facirbelt 295er	Reloader Used:

Brand of cleaning solution used: TIT Bhuk Put. Bore Solvent
How often do you clean the bore? (Months or Number of rounds) Every 2 ਸਦੇ ਨਾ ਤੌਰਦੇ ਤੁੰਦਾਂ
How often do you clean the action? (Months or Number of rounds) After 2n2 or 3rl shot
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Rem. oil
How often do you lubricate the bore? (Months or Number of rounds) こっとって 3rと にと
How often do you lubricate the action? (Months or Number of rounds) シルとって ろくし にと
How often do you lubricate the trigger assembly? (Months or Number of rounds) for 2 times yearly
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? >□ YES ☑ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

Factory Repair Form

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/8/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACK	(A) 10 lbs
PLEASEICHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL XXXXX	
DESCRIPTION:	Ref# 5015 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Jimmy Baker
176 Butner Rd.
Pinnacle, NC 27043
Ph: 336-325-2401

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 NOV 9, 2010 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKINGH 1Z4XX5969067957649 1 OF 1 REF 1: JIMMY BAKER/CD/DMF REF 2:5015/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHROS: SVC T/P USD COD 9 06 RS 0 50 00.0 VG DGD 0 00 PR 0 00 SD 0.00 DC 0.00 SP 0.00 AH 0.00 PR PUB+HANDL INC TOT PUB CHG 8.20





