PrintBis	R B E R B E R B E R - Ki	inzer PPS GA	AL RE 00103	349						I	Page 1 of 3	
				Remington A	Arms Co.,	Inc.						
				U	Service							
				Legal Ca	se #:5483							
Case Infor	mation											
	E# 5/217688	Date Opened 1/6/2011	Date Ope 12/21/		Date ( 1/7/2	Closed 2011	Incident I	Date	Pre Lit	Lit	Obsolete X	
Customer	Information											
Туре	Business	First Name	Last Name	Str	eet	City	State	Zip	Age	C	ontact	
Incident		Dan	Cook	34496 M	arina Ct	Westland	I MI	48185		H 734	-788-1541	
Incident In	formation											
	Claims		Codes			Repair Es	t. Med	lical Tre	atment	Med	ical Status	
PI												
PD		Cause	:4013 Broken	or Missing P	arts			Unknov				
S Fire	d on safe relea	ise Conce	rn:1007 Fired or	1 Safe Releas	e			UNKNOV	V11			
<u> </u>												

С

12/21/10 Per email sent to Remington.com, incid # 101220-000079, "I have a 54 cal 700ML and while hunting this week I moved the safety to fire on a deer and the gun fired without me touching the trigger. I bought this rifle in 1996 to match my 700 7MM mag, both in SS with syn. stocks and have used both on many hunts without a problem. The rifle has never been modified in any way. What do I do to correct this problem. I want to keep this rifle as it is the 54 cal. which is very rare and know of no other muzzle loaders in that cal. available today. I did go to the range and had the range officer watch me while I wrapped my fingers around the stock and used my thumb to move the safety to fire and it fired without touching the trigger two of three times. Is this something my local gunsmith can correct or must I return it to Remington? I also had it fire when just closing the bolt while the rifles safety was in the fire position. Should I also have my 7MM checked as well? I know there have been problems with this safeties and hope there is a fix that can restore my confidence in these rifles."cm

Firearm Information Mfg. Remington Date Purchased CONCERN:FSR	Type ML/BA Where Purchased OX YOKE	Model/Ga. 700ML/54 CAL Accessories 0	SKU 27582 Driginal Owner U	Serial ML056103	<b>Bbi</b> . AR	<b>DOM</b> 3/7/1997
Mfg. Remington Date Purchased A <sup>th</sup> CONCERN:CHECK TPA	<b>Type</b> CF/BA <b>Where Purchased</b> CUSPORT CORPORATION	Model/Ga. 700/7MM REM M/ Accessories	SKU A 29692 Original Owne U	Serial S6261408 er	вы. WO	DOM 8/26/1994
Ammunition Information - I Other Products Information Settlement	- None Defined	Remington/700ML/ML/BA	A			
Settlement Per Ilion, for 700 replace T at 1/2 normal cost for M	<b>Release of Claims</b> PA	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	. Cash Date APV
repair at no charge	Repair/Replacement Cost 40.75	Repair/Replacement Date 1/19/2011				
replace TPA at 1/2 normal c	ls.cm 1/19/11 For repair 21768 cost. For repair 217656, the 700 repair # 217688 be returned as	ML will be repaired at no	d faults. Trigger assm o charge, including a n	functions as des ew TPA. On 1/1	igned. C 0, Cook	Can offer to c spoke with
Examination[Remington/M]	L/BA]			aften felder an generale speler Mill Mill (1997). Bit is a standarden		

Part	Sub-Part	Code	Comment
1			

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5483&Type=Case

1/20/2011

	Examiner		<b>B.TRAVIS</b>
	Exam Date		1/7/2011
Examination	Product Type		RF
:	Action Type		A
	Assigned To		T.NAGLE
Cause	4013	Broken or Missing Parts	VERY CLEAN AND WELL KEPT
	Description		24" 54 CAL SS
	Date Code		AR
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Keceiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	N/A
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Slightly Worn; Not Functioning	CONNECTOR BROKEN
Trigger	Pull	Select	N/A
	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		<b>B.TRAVIS</b>
	Exam Date		1/7/2011
Examination	Product Type		RF
	Action Type		Α
	Assigned To		T.NAGLE
Cause	4039	No Fault Found	
	Description		24" 7MM REM MAG SS
	Date Code		WO
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5483&Type=Case

1/20/2011

## Print BARBER - Kinzer PPS GAL RE 0010351

	Shroud	Slightly Worn; Functioning	
Delt	Face	Slightly Worn; Functioning	
Bolt	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Block Condition	Sclect	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
<u> </u>	Lift	Select	.016
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
	Condition	Like new; Functioning	
Tricoar	Pull	Select	5#
Trigger	Altered	False	
	Sub-Assembly	M/700 Non-Bolt Lock	

1/20/2011

BARBER - Kinzer PPS GAL RE 0010352



December 21, 2010

Dan Cook 34496 Marina Ct Westland, MI 48185

Subject: #5483, Model 700

Dear Mr. Cook,

B6261408

RE0021/688

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. <u>Please mark the ends of the</u> boxes with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

BY:

Could Find No faults T.A. functions As Designed. CAN offer to Rephase TPA AT 1/2 NOR MAL COST.

Retar Red Vic A.S.sco

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Model Number: 700	Serial Number: 56261408
Are you the original owner?: $X_{YES}$ $\Gamma_{NO}$	
Name: DANNY COOK o	Date of Purchase: 1995
Address (no PO Boxes): 34496 MA	RINA CT
city: WESTLAND	State: MICH zip: 48185
Phone (Daytime): 734-788-1541	Fax:
E-mail Address:(if e-mail address is provided, notification sent) DRCCOOK @ ComCr	
E-mail Address: K I would like to receive future e-mail updates from Re	mington.
Please describe your problem and date of occurrence HAVE HAD A PREVBLOM C 700 AND WANT TO BE IS OK	
500	
Ammunition Information:	
Manufacturer:	Тура:
Other (i.e. bullet weight/type, shot size, powder):	
Handload Information:	
Powder Used:	Powder Weight:
Case/Huil Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

NOTE: Please complete and print this form, and then include it with your firearm.

Response (Chris)

12/21/2010 01:43 PM

Dan, I will go ahead and send another label for the other 700. It will be mailed from NC so hopefully you will have it next week. Customer (Dan cook) 12/21/2010 09:41 AM

## Christy

I would like to send my 700 7mag in as well. There have been no issues with the 7mag but would feel better to know it is safe as well. Dan Customer (Dan cook) 12/20/2010 04:11 PM

## Christy

Yes I would like to send my rifle in for inspection. You can send the UPS label to Danny Cook 34496 Marina ct. Westland, Michigan 48185-1490 <u>drccook@comcast.net</u> 734-788-1541 Thank you for the quick response. Danny Cook

----- Original Message -----From: "Remington Information" To: <u>drccook@comcast.net</u> Sent: Monday, December 20, 2010 1:25:00 PM Subject: 700ML Safety [Incident: 101220-000079]

#### Response (Chris)

12/20/2010 01:25 PM

Dan, I would recommend letting us inspect the rifle before using this muzzle loader. I can send you a prepaid UPS ground shipping label to cover shipment to the factory for inspection. Let me know what address to mail it to. We can give you a call after inspection.

## Sincerely,

Christy Mitchell

Customer (Dan cook)

12/20/2010 09:59 AM

I have a 54 cal 700ML and while hunting this week I moved the safety to fire on a deer and the gun fired without me touching the trigger. I bought this rifle in 1996 to match my 700 7MM mag, both in SS with syn. stocks and have used both on many hunts without a problem. The rifle has never been modified in any way. What do I do to correct this problem. I want to keep this rifle as it is the 54 cal, which is very rare and know of no other muzzle loaders in that cal, available today. I did go to the range and had the range officer watch me while I wrapped my fingers around the stock and used my thumb to move the safety to fire and it fired without touching the trigger two of three times. Is this something my local gunsmith can correct or must I return it to Remington? I also had it fire when just dosing the bott while the rifles safety was in the fire position. Should I also have my 7MM checked as well? I know there have been problems with this safeties and hope there is a fix that can restore my confidence in these rifles. I must say that both rifles are the most accurate ones I own. The 7mm mag shoots 1/2" groups @100yds. with 165 grain Winchester ballistic tips. This rifle drooped a 300 class elk @ 350yds. three years ago so you can see why I want to keep this rifle. Thanks Dan

drccook@comcast.netdrccook@comcast.net> Phone 734-788-1541

## http://sz0023.ev.mail.comcast.net/zimbra/public/blank.html

## 12/28/2010

~ 27 Aiz 3/47

December 21, 2010

Dan Cook 34496 Marina Ct Westland, MI 48185

Subject: #5483, Model 700

Dear Mr. Cook,

 讃ML056103

700N

E0021765

Model:

Thank you for your patience. Enclosed is the UPS ground prepaid shipping label to cover shipment of the firearm for inspection at our factory. Please include a copy of this letter with the firearm. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. <u>Please mark the ends of the</u> boxes with "Product Service".

I apologize for the inconvenience that this incident has caused and I hope that these actions will keep you a loyal Remington customer.

Sincerely,

Christy Mitchell Consumer Affairs Administrator Phone: 800-243-9700, ext 8684 christy.mitchell@remington.com

三日のほよで 町 Ιń JAN 1 2 2011 BY:....

15

REPHACE TOA, CLARKOWER, CLEANSE REPHACE TOA, CLARKOWER, CLEANSE REPAIRAS Needed AT N/C #230145

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com While hunting this week I moved the safety to fire and the gun fired without me touching the trigger. I bought this rifle in 1996 and have until now never had a problem. I did go to the range and had the range officer watch me while I wrapped my fingers around the stock and used my thumb to move the safety to fire and it fired without touching the trigger two of three times. I also had it fire when just closing the bolt while the rifles safety was in the fire position. Danny Cook 34496 Marina ct. Westland Mich. 48185 drccook@comcast.net

734-788-1541

http://sz0023.ev.mail.comcast.net/zimbra/public/blank.html

12/28/2010

.. **.**.

. ... ------

Model Number: ML 700	Serial Number: ML056103
Are you the original owner?: XYES NO	
Name: DANNY COOKO	Date of Purchase:
Address (no PO Boxes): 34496 MA	eina ct
City: WESTLAND	state: MUCH Zip: 48185
Phone (Daytime): 734-788-1541	Fax:
E-mail Address: (if e-mail address is provided, natification sent) DECCOOK & COMCA	
E-mail Address:	
I would like to receive future e-mail updates from Re	emington.
Please describe your problem and date of occurrence	8:
GUN FILES WHEN S TO FILE WITHOUT T	ZUCHING THE TRIGGER
ALSO FIRES WHEN	BOLT is CLOSEAND THE
SAFETY is IN FIR	of position.
- ,	,
	억
500 characters left	
Ammunition Information:	•
Manufacturer:	Туре:
Other (i.e. bullet weight/type, shot size, powder).	· · · · · · · · · · · · · · · · · · ·
Handload Information:	
Powder Used:	Powder Weight
Gase/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:

NOTE: Please complete and print this form, and then include it with your firearm.

## Inciderare Ber 20 Kin 2017 PPS COALL Reform 0358

#### Reference # 101220-000079 Status Updated Assigned To Administrators Christy -Product Firearms SLA

Not specified Queue

CSR

## Date Created

12/20/2010 09:59 AM Initial Response 12/20/2010 01:25 PM

Last Updated 12/21/2010 03:42 PM

## Customer SmartSense

+1 (on -3 to +3 scale) Staff SmartSense 0 (on -3 to +3 scale)

## 700ML Safety

Discussion Thread Customer (Dan cook) Christy Thank you. Have a great Christmas. Dan Cook ---- Original Message ----From: "Remington Information" Ta: drccook@comcast.net Sent: Tuesday, December 21, 2010 1:43:26 PM Subject: 700ML Safety [Incident: 101220-000079]

### Response (Christy -)

Dan, I will go ahead and send another label for the other 700. It will be mailed from NC so hopefully you will have it next week.

## Customer (Dan cook)

Christy I would like to send my 700 7mag in as well. There have been no issues with the 7mag but would feel better to know it is safe as well. Dan

## Customer (Dan cook)

Christy Yes I would like to send my rifle in for inspection. You can send the UPS label to Danny Cook 34496 Marina ct. Westland, Michigan 48185-1490 <u>drccook@comcast.net</u> 734-788-1541 Thank you for the quick response. Danny Cook

----- Original Message -----From. "Remington Information" To: drccook@comcast.net Sent: Monday, December 20, 2010 1:25:00 PM Subject: 700ML Safety [Incident: 101220-000079]

#### Response (Christy -)

Dan, I would recommend letting us inspect the rifle before using this muzzle loader. I can send you a prepaid UPS ground shipping label to cover shipment to the factory for inspection. Let me know what address to mail it to. We can give you a call after inspection.

Sincerely, Christy Mitchell

#### Customer (Dan cook)

12/20/2010 09:59 AM

12/20/2010 01:25 PM

I have a 54 cal 700ML and while hunting this week I moved the safety to fire on a deer and the gun fired without me touching the trigger. I bought this rifle in 1996 to match my 700 7MM mag, both in SS with syn, stocks and have used both on many hunts without a problem. The rifle has never been modified in any way. What do I do to correct this problem. I want to keep this rifle as it is the 54 cal, which is very rare and know of no other muzzle loaders in that cal, available today. I did go to the range and had the range officer watch me while I wrapped my fingers around the stock and used my thumb to move the safety to fire and it fired without touching the trigger two of three times. Is this something my local gunsmith can correct or must I return it to Remington? I also had it fire when just closing the bolt while the rifles safety was in the fire position. Should I also have my 7MM checked as well? I know there have been problems with this safeties and hope there is a fix that can restore my confidence in these rifles. I must say that both rifles are the most accurate ones I own. The 7mm mag shoots 1/2" groups @100yds. with 165 grain Winchester ballistic tips. This rifle drooped a 300 class elk@ 350yds. three years ago so you can see why I want to keep this rifle. Thanks Dan drccook@comcast.net/

## **Primary Contact**

First Name: Dan Last Name: cook Organization: Login: drccook@comcast.net Title: Contact Type: Email: drccook@comcast.net Email - Alternate #1: Email - Alternate #2: Office Phone: Mobile Phone: Fax: Assistant Phone: Home Phone: Street City State/Province **Postal Code** Country

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc\_print.php?p\_sid=... 12/22/2010

12/21/2010 03:42 PM

12/21/2010 01:43 PM

12/21/2010 09:41 AM

12/20/2010 04:11 PM



Remington.

www.remington.com

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

# ARS LABEL REQUEST FORM

DATE:	12/21/2	010 REQUESTED BY:	christy	
QUANTITY:	(2)	WEIGHT PER PACKA	GE:	10
RIEASEICHECKIONES MEDIA COORDINATOR TO MAIL	<i>Y</i>	I WILL MAIL	xxx	
DESCRIPTION:	700ML & 700			

# LABEL INFORMATION

MAIL LABEL TO:	Danny Cook 34496 Marina ct. Westland, Michigan 48185-1490
RETURN ITEM TO:	Rem Product Service

PLEASE COMPLEME ALLEPARTS OF THIS FORM, AND SEND TO THE MEDIA COORDINATION

4XX596 DEC 21, 2010 ALL CURR USD SVC GNDCOM TRACKING# 1Z4XX5969065778560 REF 1:DANNY COOK/CD/CM REF 1:DANNY COOK/CD/CM		4XX596 DEC 21, 20 SVC GNDCOM AC TRACKING# 1Z4XX596906577 REF 1:DANNY COOK/CD/CM REF 2:700		JSD 20F2
REF 1:000 ML REF 2:700 ML SVC	0.50 0.00 0.00	HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CH DV 0.00 COD DC 0.00 DGD AH 0.00 PR TOT PUB CHG 8.24	0.00 0.00	/C T/P USD RS 0.50 SD 0.00 SP 0.00 8.24





