

BARBER - Kinzer PPS GAL RE 0010503

Remington Arms Co., Inc.

Product Service

Legal Case #:5074

Case Information

| RE# | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|-----|-------------|-----------------|-------------|---------------|---------|-----|----------|
| | | 11/12/2010 | | | | | |

Customer Information

| Type | Business | First Name | Last Name | Street | City | State | Zip | Age | Contact |
|----------|----------|------------|-------------|-------------------|-------------|-------|-------|-----|----------------|
| Incident | | Vincent | DelBroccolo | 1607 Winding View | San Antonio | TX | 78260 | | H 830-980-5552 |

Incident Information

| Claims | Codes | Repair Est. | Medical Treatment | Medical Status |
|--------|------------------------|---|-------------------|----------------|
| PI | | | | |
| PD | | | | |
| S | Fires when bolt closed | Cause:4079 Other - Unexamined Concern:1008 Fired on Bolt Closing | | Unknown |
| C | | | | |

11/12/10 Per call from DelBroccolo, he has a 700 BDL 22-250 and sometimes when he goes to close the bolt it fires. It just started this year. He had not shot it for about 12 years prior due to shoulder surgery. He did not clean the trigger or safety before shooting after all this time. He put some oil in the chamber before shooting.cm

Firearm Information

| Mfg. | Type | Model/Ga. | SKU | Serial | Bbl. | DOM |
|----------------|-----------------|-------------|----------------|--------|------|----------|
| Remington | CF/BA | 700/22-250 | n/a | 261294 | | 1/1/1967 |
| Date Purchased | Where Purchased | Accessories | Original Owner | | | |
| | | | Y | | | |

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

| Settlement | Release of Claims | Release Date | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|------------|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| | Repair/Replacement Cost | Repair/Replacement Date | | | | |
| | | | | | | |

11/12/10 Mailing ARS.cm

Examination[Remington/CF/BA]

| Part | Sub-Part | Code | Comment |
|------|----------|------|---------|
| | | | |

Remington.

www.remington.com

Remington Arms Company, Inc.
870 Remington Drive
P. O. Box 700
Madison, NC 27025-0700

ARS LABEL REQUEST FORM

| | | | |
|-----------------------------------|------------|---------------------|---------|
| DATE: | 11/12/2010 | REQUESTED BY: | christy |
| QUANTITY: | 1 | WEIGHT PER PACKAGE: | 10 |
| PLEASE CHECK ONE: | | | |
| MEDIA COORDINATOR TO MAIL | | XXXXXXXXXX | |
| | | I WILL MAIL | |
| DESCRIPTION: 700 261294 | | | |

LABEL INFORMATION

| | |
|-----------------|---|
| MAIL LABEL TO: | Vincent DelBroccolo 1607 Winding View San Antonio, TX 78260 |
| RETURN ITEM TO: | Rem Prod Serv Ilion, NY |

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 NOV 12, 2010 ALL CURR USD 1 OF 1
 SVC GND COM ACT WT 10.0 LBS
 TRACKING# 1Z4XX5969067024790
 REF 1: VINCENT DELBROCCOLO/CD/CM
 REF 2: 700/261294

HANDLING CHARGE 0.00
 SINGLE-PIECE PUB RATE CHRGs:
 DV 0.00 COD 0.00 SVC T/P USD
 DC 0.00 DGD 0.00 RS 0.50
 AH 0.00 PR 0.00 SD 0.00
 TOT PUB CHG 10.54 PUB+HANDLING 10.54