Remington Arms Co., Inc.
Product Service
Legal Case #:5413

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete 217413 1/4/2011 12/13/2010 1/6/2011

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Reporter Larry Matchak 1500 Sandy Lane Hermitage PA 16148 H724-962-4637

E lmatchak@verizon.net

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

PΙ

PD Cause:4038 Could Not Duplicate Concern Unknown

S Concern:1007 Fired on Safe Release

C FSR

Customer sent in an email. He stated that his son was currently using the Model 700 that was his father's. His father bought the rifle around 1972. He stated that his father & his son have had a FSR. No damage, No injury. He would like to have trigger replaced. df

Firearm Information

Mfg. Туре Model/Ga. SKU Serial Bbl. DOM 700/3006 SPRG CF/BA Remington n/a 311943 10/1/1967 EP Date Purchased Where Purchased Accessories **Original Owner** TWP PIECE BASE N

CONCERN:FSR

Ammunition Information - None Defined
Other Products Information - None Defined
Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Reimbursement Reimbursement Release Date Reimbursement Reimbursement Release Date Reimbursement Release Date Reimbursement Release Date Release Date Release Date Reimbursement Release Date Release Date Release Date Reimbursement Release Date Releas

Per Ilion - Quote to repair under BLM program

Repair/Replacement Cost Repair/Replacement Date

\$45.40 1/17/201

12/13/10: I will email ltr & form. I will ask media coord. to email ARS. df 1/17/11: Per Ilion - Could not duplicate concern. TA very dirty & sticky, parts work sluggish. Replace TA, clean & test fire under BLM program - quote. Customer apprvd repair & paid by credit card. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/6/2011
	Product Type		RF

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5413&Type=Case

1/17/2011

	Action Type		ام
	Assigned To]	T.NAGLE
Cause	4038	Could Net Double to Conse	1.NAGLE
Cause	<u> </u>	Could Not Duplicate Concern	
Barrel	Description]	22" 3006 SPR
	Date Code	<u></u>	EP
	Bore Plugged	False	
	Bulged	False	<u> </u>
	Fired	False	1
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning]
	Condition	Slightly Worn; Functioning]
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select]
Locking	Lug Condition	Slightly Worn; Functioning]
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning]
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Di	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	SLUGGISH
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	DIRTY,STICKY
T-!	Pull	Select	6#
Trigger	Altered	False	
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWP PIECE BASE

Remington

5413

December 13, 2010

Larry Matchak
1500 Sandy Lane
Hermitage, PA 16148
Ph: 724-962-4637
Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

M JAN 1 ^ 2011

enclosure

311943 Model: 700

RF00217413

could not dupli wate concern T. A. very disty a sticky, parts works luggish slephace TPA, cleant test Rise under BLP Cor \$ >0.00 + ship.

Quote

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

3°°°

Print Reset					
Model Serial					
Number: 700	Number: 3/1	943			
Are you the original owner?: 🖺 YES 📓 NO					
Name: LARRY MATCHAIC Date of Purchase:					
Address (no PO Boxes):					
1500 SANDY LA					
City: HERMITAGE	State: PA.	Zip: 161-18			
Phone (Daytime): フュケータしユーサレンフ Fax:					
E-mail Address: (if e-mail address is provided, notification of receipt and shipment will be sent) MATCHAK & VERIZONO NET					
E-mail A					
☑ I would like to receive future	e-mail updates from Re	emington.			
Please describe your proble		ence:			
ACCIDENTAL FI	RING WHEN				
SAFETY IS TAK	EN OFF.	in Arthur and			
THIS HAPPENE	o on 20th	ASSIONS			
ONEE APPROX. 20 ONCE A COUPLE	YEARS AGO,	, +			
ONCE A COUPLE	WEEKS AGO	9 . :			
	SEE ATTACHED LETTER &				
500 cha	racters left				
Ammunition Information:					
Manufacturer: REMINGTON	Manufacturer: REMINGTON Type: CORE-LOKT				
Other (i.e. bullet weight/type, shot size,					
powder): 1504180	GRAIN				
	····				
Handload Information:					
Powder Used: Powder Weight:					
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					

LARRY MATCHAK
1500 SANDY LANE
HERMITAGE, PA. 16148
PH# 724-962-4637
REF#5413 COPY OF ORIGINAL E-MAIL SENT

MY SON IS PRESENTLY USING HIS GRANDFATHERS REMINGTON MODEL 700 30-06 BOLT ACTION RIFLE. THIS GUN WAS PURCHASE BY MY FATHER IN 1972. BETWEEN MY SON AND MY FATHER THERE HAS BEEN 2 ACCIDENTAL FIRINGS OVER THE YEARS WHEN THE SAFETY IS TAKEN OFF. I UNDERSTAND THAT THERE HAS BEEN THIS TYPE OF PROBLEM WITH THIS RIFLE DATING WAY BACK. I AM NOT INTERESTED IN ANY LAW SUITS BUT WOULD FEEL MUCH BETTER KNOWNING THE GUN IS SAFE. I UNDERSTAND THAT THERE IS A REPLACEMENT TRIGGER THAT WILL SOLVE THE PROBLEM. I BELIEVE THAT IT IS THE X-MARK PRO TRIGGER ASSEMBLY. SO FAR I HAVE BEEN TOLD BY SEVERAL GUN DEALERS THAT I HAVE TO SEND THE RIFLE TO THE FACTORY TO GET THIS DONE. IF THIS IS TRUE WHERE DO I SEND IT AND HOW MUCH WILL IT COST? I WOULD APPRECIATE ANY HELP YOU CAN GIVE ME. SERIAL NUMBER ON THIS RIFLE IS #311943. THANK YOU

Brand of cleaning solution used: OUTER'S + Hoppe's
How often do you clean the bore? (Months or Number of rounds) AFTER USAGE DEPENDED OF CONDITION
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds) ンピルパレン
Brand of lubricant used: Outers of Hoppe's
How often do you lubricate the bore? (Months or Number of rounds) YERRLY - BEFORE STO RING AWAY
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > 回 YES 图 NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

12/13/2010 09:56 AM

Reference # 101209-000045

Status Updated

Assigned To Administrators

Dell -Product

Firearms

Not specified

Queue CSR

Date Created 12/09/2010 12:12 PM

Initial Response 12/13/2010 08:51 AM

Last Updated 12/13/2010 09:56 AM

Customer SmartSense 0 (on -3 to +3 scale)

Staff SmartSense +1 (on -3 to +3 scale)

REMINGTON MODEL 700 BDL

Discussion Thread

Customer (Larry Matchak)

HERE IS THE INFORMATION YOU REQUESTED:

RIFLE SERIAL #311943 CAL. 30-06

MAILING ADDRESS: LARRY MATCHAK 1500 SANDY LANE

HERMITAGE, PA. 16148 PHONE # 724-962-4637

---- Original Message ---From: Remington Information
To: Imatchak@verizon.net

Sent: Monday, December 13, 2010 8:51 AM

Subject: REMINGTON MODEL 700 BDL [Incident: 101209-000045]

Response (Dell -)

Dear Mr. Matchak,

We would like to have the firearm come into our Product Services Department at our factory for examination. Please reply back to me with the serial number of the firearm, caliber, your mailing address and phone number. We would like to send you a pre-paid shipping label for UPS to have the firearm come in. I will also include a form that you can fill out to let the examiner know exactly what happened, when this occurred, and

what you are expecting. Sincerely,

Dell

Customer (Larry Matchak)

12/09/2010 12:12 PM

12/13/2010 08:51 AM

MY SON IS PRESENTLY USING HIS GRANDFATHERS REMINGTON MODEL 700 BDL 30-06 BOLT ACTION RIFLE. THIS GUN WAS PURCHASE BY MY FATHER IN 1972. BETWEEN MY SON AND MY FATHER HAS BEEN 2 ACCIDENTAL FIRINGS OVER THE YEARS WHEN THE SAFETY IS TAKEN OFF. I UNDERSTAND THAT THERE HAS BEEN THIS TYPE OF PROBLEM WITH THIS RIFLE DATING WAY BACK. I AM NOT INTERESTED IN ANY LAW SUITS BUT WOULD WOULD FEEL MUCH BETTER KNOWNING THE GUN IS SAFE. I UNDER STAND THAT THERE IS A REPLACEMENT TRIGGER THAT WILL SOLVE THE PROBLEM. I BELIEVE THAT IT IS THE X-MARK PRO TRIGGER ASSEMBLY. SO FAR I HAVE BEEN TOLD BY SEVERAL GUN DEALERS THAT I HAVE TO SEND THE RIFLE TO THE FACTORY TO GET THIS DONE. IF THIS IS TURE WHERE DO I SEND IT AND HOW MUCH WILL IT COST? I WOULD APPRECIATE ANY HELP YOU CAN GIVE ME. SERIAL NUMBER ON THIS RIFLE IS #311943. THANK YOU

Primary Contact

First Name: Larry Last Name: Matchak

Organization:

Login: Imatchak@verizon.net

Title: Contact Type:

Email: Imatchak@verizon.net

Email - Alternate #1: Email - Alternate #2:

> Office Phone: Mobile Phone: Fax: Assistant Phone:

> > Home Phone: Street

Street City State/Province Postal Code Country

Additional Information

Model_Number: 700

5413

http://remington.custhelp.com/cgi-bin/remington.cfg/php/admin/display/inc_print.php?p_... 12/13/2010



December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637

Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



December 13, 2010

Larry Matchak 1500 Sandy Lane Hermitage, PA 16148 Ph: 724-962-4637

Email: lmatchak@verizon.net

Ref: #5413

Dear Mr. Matchak,

You will receive a pre-paid shipping label in a separate email within 24-48 hours. Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

Fax: 336-548-7872

I hope that this action will keep you a loyal Remington customer.

Sincerely, D. Fulcher Consumer Affairs Administrator Remington, H&R, Marlin Phone: 1-800-243-9700

enclosure

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

Print		Reset				
Model Number:		Serial Number:				
Are you the original owner?: YES NO						
	ingiliai owi		Purchase:			
Name:						
Ad	dress (no	PO Boxes):				
City:		State:	Zip:			
Phone (Daytime):		Fax:				
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent)						
I would like to rece	E-mail Address: I would like to receive future e-mail updates from Remington.					
500 characters left						
Am	munition I	nformation:				
Manufacturer:		Type:	2 S			
Other (i.e powder):	. bullet wei	ght/type, shot size,				
H	andload In	formation:				
Powder Used:		Powder Weight:				
Case/Hull Used:		Primer Used:				
Bullet Type/Shot Size:		Reloader Used:				
Firearms Ca	re (Cleani	ng and Lubrication):				

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☑ YES ☑ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.

BARBER - Kinzer PPS GAL RE 0011510

Fulcher, Dell Marie

From:

Verizon Online Postmaster [postmaster@verizon.net]

To:

Imatchak@verizon.net

Sent: Subject: Monday, December 13, 2010 5:13 PM Delivered: Larry Matchak - Ref# 5413

Your message has been delivered to the following recipients:

Imatchak@verizon.net

Subject: Larry Matchak - Ref# 5413





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	12/13/2010	RE	QUESTED BY:	Dell		
QUANTITY:	1	WE	IGHT PER PKG:		10 lbs	
PLEASE CHECK ONE						
MEDIA						
COORDINATOR	XXXXXX	E.				,
TO MAIL		<u> </u>			<u> </u>	
DESCRIPTION:	Ref # 5413					
	rifle		4XX596 DEC SVC GNDCOM	14, 2010 ACT	ALL CURR WT 10.0 LBS	USD 1 OF 1
	•		TRACKING# 1Z4XX5 REF 1:LARRY MATC REF 2:5413/RIFLE	HAK/CD/Dr		
	LABEL II	NF(HANDLING CHARGE SINGLE-PIECE PUB DV 0.00 DC 0.00 AH 0.00 TOT PUB CHG 7.92	RATE CHR COD DGD PR	0.00 0.00 0.00	SVC T/P USD RS 1.00 SD 0.00 SP 0.00
MAIL LABEL TO:	Larry Matchak		101 Pub CHG 7.92		PUB+HANDLING	7.92
	1500 Sandy Lane					
	Hermitage, PA 16148					1
	Ph: 724-962-4637					
	Email: lmatchak@verizon.ne	et		Email:to	customer	
RETURN ITEM TO	Remington Arms					
	Attn: Product Service					
	Ilion, NY					'
	·					
		_				
		=				

UPLEASE COMPLETE ALL PARTIS OF THIS FOR

Imatchak@verizon.net







