## BARBER - Kinzer PPS GAL RE 0011730

Remington Arms Co., Inc. Product Service Legal Case #:4679

Case Information

 RE#
 Date Opened
 Date Opened(PS)
 Date Closed
 Incident Date
 Pre Lit
 Lit
 Obsolete

 200297
 8/10/2010
 8/17/2010
 8/17/2010

Customer Information

Zip Type Last Name Street City State Contact **Business** First Name Age H 832-588-4333 3769 Lazy River Dr. Reporter Clarence M. Noack III Sealy TX 77474 E noack920@yahoo.com

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Cause: 4038 Could Not Duplicate Concern
S Fired on Bolt Closing Concern: 1008 Fired on Bolt Closing Unknown

С

Customer wrote in a note: The gun fired prematurely. Every time he closed the bolt the firing pin released. He found a screw that was loose on the trigger & tightened it up. Seemed to fix the problem. Accuracy is poor. dmf

Firearm Information

Model/Ga. SKU Bbl. DOM Mfg. Serial Type 700/338 LAPUA 25645 G6945149 KE 5/19/2010 1:38:16 PM CF/BA Remington Original Owner **Date Purchased** Where Purchased Accessories

Y

7/8/2010 BAILEY S FIREARMS COUNTRY CONCERN:FIRED PREMATURELY

Ammunition Information - None Defined
Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement APV APV

Per Ilion - Repair under warranty

> Repair/Replacement Repair/Replacement Cost Date

\$195.85 8/19/2010

8/19/10: Per Fred S. - Could not duplicate concern. Check over, replace tpa to restore confidence in rifle. Function check & test fire. Warranty. dmf

## Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		8/17/2010
	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 338 LAPUA MB
	Date Code		KE
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		


http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4679&Type=Case

8/19/2010

	Muzzle/Crown Condition	Like new; Functioning		
Bolt	Firing Pin	Like new; Functioning		
	Shroud	Like new; Functioning		
	Face	Like new; Functioning		
	Handle	Like new; Functioning		
	Stop	Like new; Functioning		
Extractor	Condition	Like new; Functioning		
	Cut Condition	Like new; Functioning		
	Ext/Eject Test	False		
	Block Condition	Select		
Locking	Lug Condition	Like new; Functioning		
	Notch Condition	Select		
	Condition	Select		
Magazine	Box Condition	Like new; Functioning		
	Exterior Condition	Like new; Functioning		
Overall	Stock Condition	Like new; Functioning		
	Fore End Condition	Select		
Receiver	Condition	Like new; Functioning		
	Bulged	False		
Safety	Description		STANDARD M/700 SAFETY	
	Function	Like new; Functioning		
	Sub-Assembly	Non-ISS		
Sear	Lift	Select	.011	
	Notch	Like new; Functioning		
	Tests	Test Fired	False	
Feeding Test	Tesis	False		
Trigger	Condition	Like new; Functioning		
	Pull	Select	5#	
	Altered	False	40X STYLE TPA	
	Sub-Assembly	M/700 Non-Bolt Lock		

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4679&Type=Case

8/19/2010



	NECEIVE Aug 182010				
	AUG	1	8	2010	
B`	Y:				

4679

24" 24" 54 011

The first time I shot the gun and tried to load another round the gun fired prematurely. Every time I closed the bolt, even with out a around in the chamber, the firing pen released. I looked at the trigger and there is a set screw that is right by the bolt release and the screw was wobbly so I tightened the screw a little and that fixed the premature firing issue. However, every time you shoot the gun after you lift the bolt the bolt will not open correctly. One has to force the bolt to open. Also the accuracy is very poor. I don't know if the problem I am having contributes to the poor accuracy or not. I have used factory ammo with 250 and 300 grain projectiles. I have 3 other Remington rifles and am very please with all. I hope you can find out what the cause is for the issues I am having with the gun. I intended on using this gun on an elk hunt at the end of October.

Thanks,

Clarence M. Noack III 832-588-4333

3769 Lazy River Dr. Sealy, Tx 77474



Could not dupliente concern check over, replace TPA TO restone confidence in rifle, function check + Test fine.

warrany

## Remington.

Factory Repair Instructions (NOTE: Please print and complete this form, and then include it with your firearm.) Model Number: 700 Serial Number: 669 45 149 Are you the original owner?: Date of Purchase: Name: State: Zip: 77474 City: Sealy Phone (Daytime): タスス Fax: E-mail Address: Noack920@yahoc · com I would like to receive future e-mail updates from Remington. Please describe your problem: First time Ammunition Information: Other (i.e. bullet weight/type, shot size, powder): Handload Information: A Powder Used: Powder Weight: Case/Hull Used: Primer Used: Bullet Type/Shot Size: Reloader Used: Firearms Care (Cleaning and Lubrication): Brand of cleaning solution used: Bute How often do you clean the bore? (Months or Number of rounds) How often do you clean the action? (Months or Number of rounds) 5 000 How often do you clean the trigger assembly? (Months or Number of rounds) Brand of lubricant used:

How often do you lubricate the bore? (Months or Number of rounds) 5 rounds	
How often do you lubricate the action? (Months of Number of rounds) 6 rounds	
How often do you lubricate the trigger assembly? (Months or Number of rounds): 5 rounds	•
CARLEST COMPANY OF THE STATE OF	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manuages YES	ual?
Comments:	ter tr.
ত্রস্থাস্থা এ প্রমা	Tarkey fruit
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?	lever
What were the services performed? None	o e la Gradence
green comment the address again and containing the green and an arrange of the containing the co	and the Alberta
The state of the s	Section 1
Ship your INSURED firearm by either UPS or Parcel Post to:	Arr.
REMINGTON ARMS CO., INC	,
ATTN: Arms Service Divison 14 Hoefler Ave Ilion, NY 13357	and the second
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.  :: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,	<b>ASE</b>
ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage.	i ang sa sa sa
:: Provide a return address on both the outside and inside the box. Shipments without a proper return address will be refused.	Ši ig ist
:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for damage or loss during shipment, so you may elect to purchase insurance from your carrier.	ne e
Charge repairs will be processed using the following guidelines:	
:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, pleas include your credit card number and expiration date with your gun)	e
:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.	order,