Remington Arms Co., Inc. Product Service Legal Case #:5192

Case Information

RE# **Date Opened** Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit Obsolete 12/9/2010 11/24/2010 1/10/2010 11/21/2010 213547

Customer Information

Type **Business** First Name Last Name Street City State Zip Age Contact C 308-830-1672 302 S. Thomsen Incident Jeff Shelton Minden NE 68959 F 3083821848

Incident Information

Claims Codes Repair Est. Medical Treatment Medical Status

ΡI

PD Shot hole in truck Cause: 4006 Altered Adjustments or Components

Unknown

S C FSR

11/23/10: Customer called in. He stated that he had a FSR on 11/21/10 & shot a hole in his truck. df

Concern:1007 Fired on Safe Release

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 700/25-06 REM n/a A6435632 AO 3/1/1977

Where Purchased **Date Purchased**

Original Owner Accessories

E janel1235@rcom-ne.com

WHITNEY SPTG DENVER CO

TWO PIECE SCOPE BASE N

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Cash Reim. Settlement Release of Claims Release Date Reimbursement Date Settlement Date APV APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Repair/Replacement Cost Date \$60.40 1/10/2011

11/24/10: Sending ARS, ltr, form. df 12/14/10: I called cust. & went over report. Customer wants quote sent to him so he can send in payemnt. We will replace TA, clean, test fire under BLM program. I will close file when I get parts listing. df 1/10/11: Got parts list - file closed. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner	·	B.TRAVIS
	Exam Date		12/10/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	POOR MAINTENENCE
	Description		24" 2506 REM
	Date Code		AO
Вагте1	Bore Plugged	False	
,	Bulged	False	

	Fired	False	
	Fired while Obstructed		-
	Muzzle/Crown Condition	Slightly Worn; Functioning	7
	Firing Pin	Slightly Worn; Functioning	Ī .
	Shroud	Slightly Worn; Functioning]
Bolt	Face	Slightly Worn; Functioning]
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	STICKS/SLUGGISH
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning]
	Ext/Eject Test	False]
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Not Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES/DENTS
	Fore End Condition	Select	
Reœiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.005
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	10313	False	
	Condition	Slightly Worn; Not Functioning	WILL FOLLOW DOWN DIRTY,STICKY
Trigger	Pull	Select	2.5#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

Add	l Repai	FGI Repairs r Estimate	Repair Expe		Inquiry Rep		SR Tools		Table Maintenar	nce System	Location
		frmREInquir	y - Repair Inqı	uir y	- সামান মানুক্তি মি কান	and the state of the state of	and the first arms	Carlos Services	natra kadigantah sejara.	the section where the	
	5 67 E	Repair Number	RE00213547	7 Serial: /	6435632 Model 70	0 Center Fire 0	aliber	Repairman.	The second of the con-	2 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	* Ask (* * * * * * * * * * * * * * * * * * *
	7.3	Verify Repair	地名经济	2506 RI	-M			Status:	Parked 12/10/20	0.5:34:35 AM	
	135	ADDRESS INFO	JAMATION".		NORTH WAS PROVIDED WATER BOOK OF THE STATE O	enteres de la comparta del comparta del comparta de la comparta del la comparta de la comparta del la comparta de la comparta					
			Customer	The state of the s	€ Re	eceived from	Return To			Received from	
		. Comment	JEFFREY SHELT				JEFFREY S				
			302 S THOMSEN				302 S THO	MSEN			
		Address 2	MINDEN		PO Box:		MINDEN		PO_Box:		
		State:	<u></u>	68959	Country: US		Y	Code: 68959	Country:	us :	
					Territoria de la composición del composición de la composición de		r				
				*		FFL	1 1	. 1 1			
	<i>5</i> .		ion Probl e ms E	stimate Histo	ory / Status: Shippir	ng / Billing					
			r-d Code Mad	User ID	Desc1	Des	c2. <u>♣</u> ୮.	Śķipping Hold	Cur	rent Status Parked	
	7	12/9/2010 9:	4/ New	valentds	Repair Added		4 3	Interface Holo	12/10/	2010 5:34:35 AM	
	17. ·	12/9/2010 9:	5 Maint	valentds	Repair Maintenan	ce Statu	13. 14	Estimate Sent Parts Receive		Travishw duct Services	
		12/9/2010 9:		valentds	Repair Maintenan		15: N	Passed Insper		air Location.	
	ķ		2: EmailSent	ArmEmail	Repair Received	JANE	-11	Return as Rec		ILN"	
		12/9/2010 12		 				Dermin as Der	ceivea Curr	ent Location	1300
		12/9/2010 12	2: EmailVerified	ArmEmail	Receipt	JANE	LLZ T	Has Been App	noved .	ent Location ILN	
			2: EmailVerified	ArmEmail 2	Receipt	JANE		Has Been App Internal Repai	noved Tran		
		12/9/2010 12	2: EmailVerified	ArmEmail	Receipt	JANE		Has Been App	noved Tran	· ILN	
		12/9/2010 12	2 EmailVerified	ArmEmail	Receipt	JANE		Has Been App Internal Repai	noved Tran	ILN Insfer Number	lose
		12/9/2010 12	2: EmailVerified	ArmEmail	Receipt	JANE		Has Been App Internal Repai	noved . Tran	ILN Insfer Number	lase
		12/9/2010 12 1 **********************************	2: EmailVerified	ArmEmail	Receipt	JANE		Has Been App Internal Repai	noved . Tran	ILN Insfer Number	lose
		12/9/2010 12 1 **********************************	2: EmailVerified	ArmEmail	Receipt	JANE		Has Been App Internal Repai	noved . Tran	ILN Insfer Number	lose
		12/9/2010 12 1 **********************************	2: EmailVerified	AmEmail	Receipt	JANE		Has Been App Internal Repai	noved . Tran	ILN Insfer Number	lase
		12/9/2010 12 1 **********************************	2: EmailVerified	AmEmail	Receipt	JANE		Has Been App Internal Repai	noved . Tran	ILN Insfer Number	lose
naglet		12/9/2010 12 4	2: EmailVerified		Receipt			Has Been App Internal Repai Exclude TATO	noved . Tran	esh C	close

	<u> </u>		 دلك	سادي ساسات	
	DEC	1	3	2010	
Ħ.	γ.				





November 24, 2010

Jeff Shelton 302 S. Thomsen Minden, NE 68959 Ph: 308-830-1672

Ref: #5192

Dear Mr. Shelton,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700
Fax: 336-548-7872

enclosure



Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com

BARBER - Kinzer PPS GAL RE 0012215

Print	Reset						
Model Number: 700	Serial Number: A6435632						
Are you the original owner?: YES ✓NO							
Name: Jeffery Shelton	Date of Purchase: November 1995						
Address (no PO Boxes): 302 S. Thomsen							
City: Minden	State: NE	Zip: 68959					
Phone (Daytime): 3088301672	Fax: 3083821848						
E-mail Address:(if e-mail address is provided, notification of receipt and shipment will be sent) janell235@rcom-ne.com							
E-mail Address: I would like to receive future e-mail updates from Remington.							
Please describe your problem and date of occurrence: 11/21/2010; Attempted to unload rifle, safety selector switch was moved from "safety" to "fire" in order to open the bolt action. As the selector switch was moved to "safe" the gun discharged into the side of my 1990 GMC Suburban. There were no injuries to myself or bystanders.							
Ammunition I	nformation:						
Manufacturer: Hornady	Type: -25-@) (s					
Other (i.e. bullet weight/type, shot size, powder):							
Handload In							
Powder Used:	Powder Weight:						
Case/Hull Used:	Primer Used:						
Bullet Type/Shot Size:	Reloader Used:						
Firearms Care (Cleaning	ng and Lubrication):						

BARBER - Kinzer PPS GAL RE 0012216

Brand of cleaning solution used: Rem Oil
How often do you clean the bore? (Months or Number of rounds) After Each Use
How often do you clean the action? (Months or Number of rounds) After Each Use
How often do you clean the trigger assembly? (Months or Number of rounds) After Each Use
Brand of lubricant used: Rem Oil
How often do you lubricate the bore? (Months or Number of rounds) After each use
How often do you lubricate the action? (Months or Number of rounds) Twice a Year
How often do you lubricate the trigger assembly? (Months or Number of rounds) Before Storing
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ✓ YES NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?) N/A
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.

BARBER - Kinzer PPS GAL RE 0012217

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:		11/24/2010	REQUESTED BY:	Dell
QUANTITY:	1	-	WEIGHT PER PKG:	10 lbs
PLEASE CHECKONE MEDIA COORDINATOR TO MAIL	÷		I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5192 Rifle			

LABEL INFORMATION

MAIL LABEL TO: Jeff Shelton
302 S. Thomsen
Minden, NE 68959
Ph: 308-830-1672

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

PLEASE COMPLETE ALL PARTS OF THIS FORM: AND SEND TO THE MEDIA COORDINATOR

2010 ALL CURR USD ACT WT 10.0 LBS 4XX596 1 OF 1 SVC GNDCOM ACT WT TRACKING# 124XX5969065912593 REF 1:JEFF SHELTON/CD/DMF REF 2:5192/RIFLE HANDLING CHARGE 0.00 SVC T/P USD RS 0.50 SINGLE-PIECE PUB RATE CHRGS: DV 0.00 DC 0.00 0.00 COD DGD 0.00 SD 0.00 AH 0.00 0.00 SP 0.00 TOT PUB CHG 9.45 PUB+HANDLING 9.45











