Page 1 of 2 PrintDisplay

### **BARBER - Kinzer PPS GAL RE 0012449**

Remington Arms Co., Inc. Product Service Legal Case #:5149

~		. •
( ace	Inform	าวทากก

RE# **Date Opened** Date Opened(PS) **Date Closed** Incident Date Pre Lit Lit Obsolete 213336 12/8/2010 11/19/2010 12/9/2010

Customer Information

**Business** First Name Last Name Street City Contact Type Age 9011 Sedgley Dr. 28412 C 910-538-6443 Walter Stowe Wilmington Incident

Incident Information

Repair Est. Claims Codes **Medical Treatment Medical Status** 

PΙ PD

Cause: 4006 Altered Adjustments or Components

Unknown

S Concern: 1007 Fired on Safe Release

C FSR

11/19/10: Customer called in. He stated that he had a FSR last hunting season. No damage - No injury. He heard from his gunsmith that we were replacing triggers for free. df

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. DOM Remington CF/BA 700/270 WIN 25771 E6653192 KU 5/30/2000

**Date Purchased** 

Where Purchased WAL-MART WAREHOUSE #3R Accessories

Original Owner TWO PIECE SCOPE BASE

Y

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Release Date Settlement Release of Claims Reimbursement Settlement APV APV

Per Ilion - quote to repair

#### Repair/Replacement Cost Repair/Replacement Date

11/19/10: Sending ARS, ltr, form. df 12/14/10: Per Ilion - TA set screws altered. Trigger no returning properly. Replace TA, clean, test fire at 1/2 normal charges, df 12/14/10: I contacted customer & went over our report. Explained why there was as charge for the repair. He wants me to mail the quote to him. He wants someone to look over it. He stated he would pay the quote "under duress". df

### Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
	Exam Date		12/9/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4006	Altered Adjustments or Components	
	Description	]	22" 270 WIN
	Date Code		KU
	Bore Plugged	False	
Barrel	Bulged	False	
	Fired	False	
	Fired while Obstructed	]	
	Muzzle/Crown Condition	Slightly Worn; Functioning	¬ ·

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5149&Type=Case

12/14/2010

,rinu)ispiay rage 2 of 2

## **BARBER - Kinzer PPS GAL RE 0012450**

	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	·
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	ISS	
	Lift	Select	.015
Sear	Notch	Like new; Functioning	
	Tests	Test Fired	False
Feeding Test	16315	False	
	Condition	Slightly Worn; Not Functioning	MIN TRIG RETURN
Tuinne	Pull	Select	2#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE SCOPE BASE

### QUOTATION

## ACHILIZION AND COMPANY, ANC.

870 Remington Dr. P.O. Box 700

Madison, NC 27025-0700

**ESTIMATING** 

REPORT

Parts/RBARBER - Kinsoer2PPS/GAL RE 0012451

336-548-7801

www.remington.com info@remington.com

ALL PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (4) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 15 DAYS, WE SHALL RETURN THE ITEM(S) AS RECEIVED POSTAGE DUE.

Repair Order RE00213336 Account # - R	5	Description/Serial Number E6653192		Estimate Date - 12/	8/2010 13/2010 14/2010
Customer WALTER S 9011 SEDC				Return To WALTER STOWE 9011 SEDGLEY DR.	
WILMING	TON. NC 28412	US		WILMINGTON, NC 28412 US	1 1
Phone (H)	(910)-538-6443		Fax Email		

Please Circle One VISA MC AMEX DISCOVER (	Card No	Exp. Date
PO Number		
Daytime Phone ()	Time To Call	Open Acct. <u>R</u>
Approval: Customer Signature		Date
If You Desire Any Change Pleas	se Use The Reverse Side For Your Co	
	Notice: We process checks electronic	
Reported	Problems <u>Fou</u>	<u>ind</u>

Reported	Problems Found	
M123 FORWARD TO PRODUCT SERVIO FOR INSPECTIO	CE M178	TRIG ADJ SCREWS RESET, CANNOT

## Technician's Comments Not returning poperly. To replace trigger assm, clean, test for 1/2 the normal cost. ProblemNotes

art			<u>Y/N</u>	<u>Unit</u>	<u>Percent</u>	<u>Amt</u>
POOSSON						
F3033/0B	X-MARK PRO 700 TRIG ASSB RH BLACK (O	1	N	\$94.00	50%	\$47.00
ervice						
4000114	GR-SHIPPING & HANDLING (GUN REPAIR)	1	Y	\$17.00	0%	\$0.00
4000118	GR-CLEAN	1	N	\$28.00	50%	\$14.00
4000119	GR-TEST	1	N	\$23.00	50%	\$11.50
4000294	GR-CHECK TPA	1	Y	\$17.00	0%	\$0.00
				Sub Total	:	\$72.50
				Est. Sales 7	Cax:	\$2.82
				Grand To	tal:	\$75.32

<u> </u>	te Repair Ex iry - Repair In		Inquiry	Repair Tools	CSR Tools		Table Maintenance	System	Location
Verify Repair		36 Serial:E WIN Pro	iduced 05/30/	2000 SKU 2577	Return To	Status:			
TO AND LONG THE REST	St					- · · · · · · · · · · · · · · · · · · ·		— palisana araba	
a tor. to Branch	<u>, , , , , , , , , , , , , , , , , , , </u>	Commercial	PO BOX		Janu Sedi	ALEY DR.	PO Boo		
对 多级增加 经环境的	WILMINGTON	Mark 1 777 2 779	***************************************	IS .	VI.526	Sec 144.00 co	Country		
12/8/2010	10 New	User ID lopatafl Travisbw	Repair Added		Status: New	Interface Hold Estimate Sent Parts Received Passed Inspec Return as Rec Has Been Appi Internal Repair	Ne 12/8/2010.1 lopz Repair Lo ion Lu ived Current Lo oved L	ov 0.28.31 AM staff Bench cation N	
(1-4323) (4-47-5) (4	7 100 700 400						Refresh	26 M3 (100 584-38 (100)	
Period Services (Section								STATES SEES TO SEE	e amerikan s
	Répair Number Verify Repair ADDRESS IN Name Address 2 Cuty State  Contact / Con Date 12/9/2010 12/9/2010	Repair Number RE002133  Verify Repair ADDRESS INFORMATION Customer  Name WALTER STOMACHER STOMAC	WIN Proventy Repair  ADDRESS INFORMATION:  Customer:  (Name: WALTER STOWE  Address 1: 9011 SEDGLEY DR.  Address 2: WILMINGTON  State: NC zip Code: 28412  Contact / Condition   Problems   Estimate: Histor  Date: Code: User ID: 12/8/201010 New Iopatafl  12/9/2010 2 4 Maint Travisbw  Repair Search	Repair Number: RE00213336   Seriel: 26653192, Mod WIN Produced: 05/30/Verify Repair     ADDRESS INFORMATION   Customer   General Repair Search     Address 1	Repair Number   RE00213336	Repair Number:   RE00213336     Serial:   E6553192   Model: 700   Center Fire   Caliber: 270   WIN Produced: 05/30/2000 SKU: 25771	Repair Number   RE00213336   Serial: E6553192, Model 700; Center Fire Caliber: 270   Repairment Will Produced: 05/30/2000 SKU: 25/71	Repair Number   RE00213336	Repair Number:   RE00213336

	<u>۔</u> دی دی		ائے ن	ריי. ער	F".	
7.7  ij	CEC	1	0	201	0	١
В	Y:					

# Remington

5149

November 19, 2010

1617 1012

Walter Stowe 9011 Sedgley Dr. Wilmington, NC 28412 Ph: 910-538-6443

Ref: #5149

Dear Mr. Stowe,

Enclosed is a prepaid UPS shipping label to cover shipment of your firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the box with "Product Service". Product Service will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

enclosure

E6653192 Model: 700 RE00213336 T.A. Set SCREWS Altered.

TRIQ. NOT DEFUENCE PROPERLY.

IMPLACE TOPA, CLEAN & TEST FIRE

AT 1/2 NORMAL LANGES.

Quide

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025

Phone 800-243-9700 • www.remington.com

BARBER - Kinzer PPS GAL RE 0012453

## BARBER - Kinzer PPS GAL RE 0012454

Print	Reset	
Model	Serial	
Number:	Number:	ad viciniana kan awaza a
Are you the original ow	ner?: YES NO	
Name:	Date of Purchase	<b>e:</b>
Address (no	PO Boxes):	and the second s
City:	State: Zip:	
Phone (Daytime):	Fax:	
E-mail Address:(if e-mail address is provid be sent)	ed, notification of receipt and s	hipment will
E-mail A  I would like to receive future e		1.
Please describe your proble	em and date of occurrence:	
500 cha	racters left	
Ammunition I	nformation:	
Manufacturer:	Type:	,
Other (i.e. bullet wei	ght/type, shot size,	
Handload In	formation:	
Powder Used:	Powder Weight:	
Case/Hull Used:	Primer Used:	
Bullet Type/Shot Size:	Reloader Used:	
Firearms Care (Cleania	and Lubrication):	
	Y	

## BARBER - Kinzer PPS GAL RE 0012455

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used:
How often do you lubricate the bore? (Months or Number of rounds)
How often do you lubricate the action? (Months or Number of rounds)
How often do you lubricate the trigger assembly? (Months or Number of rounds)
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? > ☐ YES ☐ NO
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Remington Arms Co., Inc. Attn: Arms Service Division 14 Hoefler Avenue Ilion, NY 13357
☐ WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
:: Record the serial number of your firearm before sending it. :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) :: Remove all accessories from your firearm to prevent loss or damage. :: Provide a return address on both the outside and inside the box. Shipments without a proper

### BARBER - Kinzer PPS GAL RE 0012456

return address will be refused.

:: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for

damage or loss during shipment, so you may elect to purchase insurance from your carrier.

Charge repairs will be processed using the following guidelines:

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card. We process checks electronically through Check21.



Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:		11/19/2010	REQUESTED BY:	Dell
QUANTITY:	1		WEIGHT PER PKG:	10 lbs
PLEASE/CHECKIONE MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXX
DESCRIPTION:	Ref # 5149 Rifle			

## LABEL INFORMATION

MAIL LABEL TO: Walter Stowe
9011 Sedgley Dr.
Wilmington, NC 28412
Ph: 910-538-6443

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

## PREASE COMPLETE ALL PARTIS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

 SINGLE-PIECE PUB RATE CHRGS:
 SVC 7/P USD

 DV 0.00
 COD 0.00
 RS 0.50

 DC 0.00
 DGD 0.00
 SD 0.00

 AH 0.00
 PR 0.00
 SP 0.00

 TOT PUB CHG 8.74
 PUB+HANDLING 8.74







