Remington Arms Co., Inc. **Product Service** Legal Case #:4882

Case Information

0

Obsolete RE# **Date Opened** Date Opened(PS) Date Closed **Incident Date** Pre Lit Lit 209884 11/10/2010 10/28/2010 11/11/2010

Customer Information

First Last Name Street State Zip Age Type **Business** Contact Name 13390 Montana Hwy Woods Bay Woods Bay Big W 406-837-MT 59911 Dan Reporter 35 Gunsmithing Gunsm Fork 1101

**Incident Information** 

Codes Repair Est. **Medical Treatment Medical Status** Claims

PΙ

PD Cause:4038 Could Not Duplicate Concern Unknown S

Concern: 1007 Fired on Safe Release

C FSR

10/27/10: Dealer called into Consumer Serv. Dept. Steve J. wrote down info & brought it to me. Dealer said consumer brought gun to him claiming FSR. Trigger has been adjusted to 1 1/2 lbs. df

Firearm Information

Model/Ga. SKU Mfg. Type Serial Bbl. DOM CF/BA 700/7MM REM MA n/a A6451746 KO 5/10/1977 Remington

Date Original Where Purchased Accessories **Purchased** Owner

ALL SPORTS SPOKANE BOTTOM HALF OF RINGED SCOPE U

WA **BASES** 

CONCERN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Reim. Cash Cash Release of Claims Release Date Settlement Reimbursement Date Date Settlement APV APV

Per Ilion - Quote to repair under BLM program

> Repair/Replacement Repair/Replacement Cost Date

> > \$54.60 11/16/2010

10/28/10: Sending ARS, ltr, form. df 11/16/10: Per Fred S. - Could not duplicate concern. TA dirty, set screws altered. Check over, replace TA, clean & test fire under BLM program - quote. df 11/16/10: I called dlr & spoke to Dan, went over report & quote. He apprvd repair & said send it out COD. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		F.SUPRY

PrintDisplay Page 2 of 3


## BARBER - Kinzer PPS GAL RE 0012872


	Exam Date		11/11/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		F.SUPRY
Cause	4038	Could Not Duplicate Concern	
	Description		24" 7MM REM MAG LH
	Date Code		КО
	Bore Plugged	False	
Barrel	Bulged	False	
Darrer	Fired	False	
	Fired while Obstructed	d	
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH/BINDS
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD M/700 BOLT LOCK SAFETY
	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
		Test Fired	False
Feeding Test	Tests	False	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=4882&Type=Case


11/16/2010

Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	Select	3#
	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		BOTTOM HALF OF RINGED SCOPE BASES





4882



October 28, 2010

Woods Bay Gunsmithing Attn: Dan 13390 Montana Hwy 35 Big Fork, MT 59911 Ph: 406-837-1101

Ref: #4882

Dear Dan,

Enclosed is a prepaid UPS shipping label to cover shipment of the firearm to our factory for examination.

Please include a copy of this letter to put inside the shipping container. The letter inside is important as sometimes the outside label gets damaged in transit and we want to be sure the firearm is logged in correctly. Mark the ends of the boxes with the name "Supry". Mr. Supry will be inspecting the firearm and will contact me with the results.

I hope that this action will keep you a loyal Remington customer.

Sincerely,
D. Fulcher
Consumer Affairs Administrator
Remington, H&R, Marlin
Phone: 1-800-243-9700

Fax: 336-548-7872

A6451746

Model: 700

RE00209884

could Not duplicate concern.
Tilig. ASSM. Disty, set Screws
plened. Clack over, suppose
TPA, clean + Testfire under
170 It cock program Ron
420.00.

Remington Arms Company, Inc. • 870 Remington Drive • P.O. Box 700 • Madison, NC 27025 Phone 800-243-9700 • www.remington.com



# Factory Repair Form

Return to Previous Page

NOTE: Please complete and print this form, and then include it with your firearm.

Model Number: 700 LH	Serial Number: A6451746
Are you the original owner?: YES	1 NO Gun Shop
Name: Dan Majerus	Date of Purchase: Woods bay Gunsm
Address (no PO Boxes): 13390	MT. Hwy 35
city: Bigfork	State: <b>MT</b> Zip: <b>599</b> //
Phone (Daytime): 406-837-	// <b>O</b> / Fax:
	led, notification of receipt and shipment will be
sent) DMAJERUS & Cer E-mail Address:	ntury telenet
I would like to receive future e-mail upd	lates from Remington.
Please describe your problem and date of	of occurrence:
	sometimes gun fires when with live round in chamber
500 characters left	
Ammunition Information:	
Manufacturer:	Туре:
Other (i.e. bullet weight/type, shot size, pow	der):
Handload Information:	
Powder Used:	Powder Weight:
Case/Hull Used:	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication)	):
Brand of cleaning solution used:	
low often do you clean the bore? (Months o	or Number of rounds)
low often do you clean the action? (Months	or Number of rounds)
low often do you clean the trigger assembly	r? (Manths or Number of rounds)
Irand of lubricant used:	
low often do you lubricate the bore? (Month	s or Number of rounds)
low often do you lubricate the action? (Mont	y
	,

	e trigger assembly? (Months or Nun	
Have you reviewed the clear YES NO	ng and maintenance recommendati	ons on our web site or in our owners manual'
When was the last time that y repairman/gunsmith?)	our firearm was serviced by a Remi	ngton authorized
What were the services period	med?)	11 / 1-11 / 1-11   11   11   11   11   1
Ship your INSURED firearm	y either UPS or Parcel Post to:	
Remington Arms Attn: Arms Servic 14 Hoefler Avenu Ilion, NY 13357	Division	
FIREARM. THIS IS A VIOLATI	N OF FEDERAL LAW. IF YOU FEEL GE AND INCLUDE NAME, ADDRESS	FIREARM OR IN THE SAME BOX WITH THE YOU MUST SEND SPENT SHELLS PLEASE SI (WITH ZIP CODE), TELEPHONE AND MODEL
ship in a firearm box. (Note: C :: Remove all accessories from :: Provide a return address on b return address will be refused :: Ship your INSURED firearm b	our firearm before sending it.  Indicate to prevent further damage in shipping its or serving in all boxes may not be returned.)  Your firearm to prevent loss or damage out the outside and inside the box. Ship or either UPS or Parcel Post. Remington the soyou may sleet to purchase insurant.	prients without a proper
Charge repairs will be processe	using the following guidelines:	
:: Repairs \$75.00 and under will credit card number and expiration		.D. (To avoid C.O.D. Charges, please include you
You will have 30 days to approv Express, Discover, MasterCard	the repair estimate. Repairs can be p	the nature of the repair, applicable taxes and ship aid by check, money order, or credit card (Americ repairs over \$75.00 by setting a pre-authorized a

© 2009 Remington Arms Company, Inc. All Rights Reserved.
Investor Relations | Other Remington Brand Products | Legal Notices | About Us

	Visit O	ur Othe	er Wel	sites
Other Sites				





Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

## ARS LABEL REQUEST FORM

DATE:		10/28/2010	REQUESTED BY:	Dell
QUANTITY:		1	WEIGHT PER PACH	(A) 10 lbs
PLEASE GHECKON MEDIA COORDINATOR TO MAIL			I WILL MAIL	XXXXXX
DESCRIPTION:	Ref# 4882 Rifle			

#### LABEL INFORMATION

MAIL LABEL TO: Woods Bay Gunsmithing
Attn: Dan
13390 Montana Hwy 35
Big Fork, MT 59911
Ph: 406-837-1101

RETURN ITEM TC Remington Arms
Attn: Product Service
Ilion, NY

#### PLEASE COMPLETE ALL PARTS OF THIS FORM; AND SEND TO THE MEDIA COORDINATOR

OCT 28, 2010 ALL CURR USD ACT UT 10.0 LBS 1 OF 1 4xX596 SVC GNDCOM TRACKINC# 124XX5969066923089 REF 1:400DS BAY GUNSMITHING/CD/DMF REF 2:4882/RIFLE HANDLING CHARGE 0.00 SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD COD 0.00 DGD 0.00 PR 0.00 RS 0.50 00.00 OC 0.00 SD 0.00 SP 0.00 PR 0.00 9.00 HA PUB+HANDLING 11.79 TOT PUB CHG 11.79