

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003599

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/19/03	Out of box Inspection	JLW1303A		
JS	12/22/03	De-Torque Scope Cross Bolt	Front 35 in lb Rear 30 in lb		
BL	12/22/03	Headspace	Min .002		
BL	12/22/03	Proof	OK	1	1
BL	12/22/03	Headspace	Min .002		
JS/BL	12/22/03	Depth Front Take down	See new hole		
BL	12/22/03	Firing Pin Indents	.020 - .021 - .021 Avg .0206		
JS	12-29-03	Sear/Trigger Engagement	Avg. .0316		
JS	12-29-03	Sear lift	.0143		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace Min +.004			
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.004		
BL	1/15/04	2nd Basic Jack Function test	Bolt hard to close w/in 5#V 30w/m2 / 5 FTE / magazine hard to take from magazine well.	2020	202
SW/BL	1/15/04	Headspace	Min .004		
JS	1-16-04	Shoulder function test	x 20 Rds.	20	222
JS/BL	1-19-04	Inspect & Clean	See Inspection sheet		

Logform

Confidential - Subpoena 19-0670003599 Order

Williams v. Remington

ET19978

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-5

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min .004☒ Sear Engagement: 1st. .0295 2nd. .0295 3rd. .0315Ave. .0301 spec- .020" to .025"☒ Trigger Pull: 1st. 4.505 2nd. 4.197 3rd. 4.307Ave. 4.336 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary. Front take down screw loose☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: locking lugs some wear, bolt stop excessive wear☒ Inspect stock for any signs of cracking or other

failure.

☒ Other items ofnote: magazine Box protruding, receiver insert has a defect must be in the mold

TLW1303

Remington Confidential

ET19979