

CAL: 300 WIN MAG

PROJECT # 241314

BARBER - 5.22.06r0003603

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS AT START-0	
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12/22/03	Do-Torque Scope Cross Bolt screw	front 30inL6 Rear 32inL6		
BL	12/22/03	Headspace	min+.002		
BL	12/22/03	Proof	Tight opening Bolt	1	1
BL	12/22/03	Headspace	min+.002		
JS/BL	12/22/03	South front Take down	min+.004		
BL	12/23/03	Firing Pin Indent.	.021-.023-.021 Avg .0206		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0272		
JS	12-29-03	Sear lift	.0175		
SW/JS	1-13-04	Charge out Bolt Head			
SW/JS	1-13-04	Headspace Min+.004			
SW/JS	1/13/04	Proof Rel		~1	2
SW/JS	1/13/04	Headspace after proof Min+.004			
SW	1/14/04	300 Rd Basic Jack Function Test		200	202
SW/BL	1/15/04	Headspace Min+.004			
H.D	1-16-04	Shoulder Function test x 20 rds.	slow FTEX3: Bolt hangs when pulled to the rear; Bolt release goes beyond stopping point.	20	222
JS/BL	1-19-04	Inspect & Clean	See inspection sheet		

Logform

ET19982

Confidential - Subject - 522.060003603 Order

Shipping - \$9.25

Williams v. Remington

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-7

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: J>/BLRound Level: 1222
☒ Measure Headspace min+.004
☒ Sear Engagement: 1st. .0278 2nd. .0278 3rd. .0276
Ave. .0278 spec. .020" to .025"
☒ Trigger Pull: 1st. 4.488 2nd. 4.599 3rd. 4.327
Ave. 4.451 spec. 4 lbs to 5.5 lb.
☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area.

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Bolt stop some wear
☒ Inspect stock for any signs of cracking or other failure.

☒ Other items of

note: Receiver insert has a defect must be in the mold, magazine box protruding

TLW1303

Remington Confidential

ET19983