

GUN # A-28

SERIAL # 71148866

CAL: 300 WIN MAG

M/710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW 1303A		
JS	12/22/03	De-Torque Scope Crosshair screws	Front 35 Rear 35		
BL		Headspace	Min + .003		
BL		Proof	OK	1	1
BL	12/22/03	Headspace	Min + .003		
JS/BL	12/22/03	Depth Front Takedown screw hole			
BL	12/23/03	Firing Pin Indent	.019 - .020 Avg .0196		
JS	12-29-03	Gear/Trigger Engagement	Arg. .031		
JS	12-29-03	Gear lift	.0138		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Headspace	Min + .005		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min + .005		
SW	1/15/04	300 Rd Basic Jack Function Test		200	202
SW	1-15-04	Headspace - Min + .005	(Front & Center Takedown screw loose)		
BL	1-16-04	Shoulder File	Bolt stop not functioning properly / 1 FT Feed	20	222
			1 FTE		
JS/BL	1-20-04	Clean & Inspect	See Inspection sheet		

Logform

BARBER - 5.22.06r0003645

CONFIDENTIAL

Remington Arms Company/Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-28

TLW #: TLW1303

Date: 01/20/04Inspector: JS/BLRound Level: 222☒ Measure Headspace mint.005☒ Sear Engagement: 1st. 030 2nd. 0302 3rd. 0302Ave. 0301 spec. 020" to 025"☒ Trigger Pull: 1st. 4.594 2nd. 5.341 3rd. 5.469Ave. 5.136 spec- 4 lbs to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area. same wear on bolt face☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Locking lugs same wear, bolt stop worn☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine box protruding

TLW1303

Remington Confidential

ET20025