

CAL: 300 WIN MAG

TRACKING # TLW 1303
PROJECT # 241314

Q. What is the difference between the two?

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START-0
				RDS. FIRED	TOTAL RDS.
SW/PR	12/14/03	Out of box Inspection			
JS	12/22/03	De-torque Scope Base Bolt Screws	Front 35 Rear 30		
BL		Head space	min t. .002		
BL		Proof	OK	1	1
BL	12/22/03	Head space	min t. .003		
JS/BL	12/22/03	Depth Front Take down Screw hole			
BL	12/23/03	Firing Pin Indents	.021-.021-.021-Aug .021		
JS	12-29-03	Sear/Trigger Engagement	Arg. .0292		
JS	12-29-03	Sear lift	.0178		
SW/JS	1/13/04	Change out bolt head			
SW/JS	1/13/04	Head space	Min t. .004		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Head space after proof	Min t. .004		
B. Lee	1/15/04	200rd Jack Funct. test	magazine Box hard to take from magazine well / 7-FTE Bolt hard to close	200	202
SW	1-15-04	Head space Min t.	.005		
BL	1-16-04	Shoulder fine	OK	20	222
JS/BL	1-20-04	Clean & Inspect	See Inspection Sheet		

Logform

ET20153

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-24

TLW #: TLW1303

Date: 01 12 104Inspector: JS/BLRound Level: 222☒ Measure Headspace min + .004☒ Sear Engagement: 1st. 0282 2nd. 0278 3rd. 0284Ave. 0281 spec. .020" to .025"☒ Trigger Pull: 1st. 4.477 2nd. 5.509 3rd. 5.271Ave. 5.086 spec- 4 lb. to 5.5 lb.☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: locking lugs same wear, bolt stop same wear☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine box protruding

TLW1303

Remington Confidential

ET20154