

TRACKING # TLW 1407
PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS	AT START - 0
				RDS. FIRED	TOTAL RDS.
JW / BL	2/16/2004	OUT OF BOX	INSPECTION OK	TLW 1407 A	
SW / BL	2/16/2004	HEADSPACE BEFORE	PROOF MIN + .004	TLW 1407 B	
SW / BL	2/16/2004	PROOF ROUND		TLW 1407 C	1 1
SW / BL	2/16/2004	HEADSPACE AFTER	PROOF MIN + .004	TLW 1407 D	
SW / JW / BL	2/16/04	INDENTS		TLW 1407 F	
SW / BL	2/17/04	SEAL LIFT	SEE DATA SHEET	TLW 1407 G	
SW / BL	2/17/04	ENGAGEMENT	↓ ↓ ↓	TLW 1407 H	
SW / BL	2/17/04	TRIGGER PULL		TLW 1407 I	
BL	2/19/04	200 Rd JACK Funct.		TLW 1407 J	200 201
BL	2/24/04	500 Rd Ext. Endur Test		TLW 1407 J	500 701
BL	3/8/04	Clean/Inspection	See Inspection Sheet	TLW 1407 K	

Logform

BARBER - 5.22.06r0004088

Confidential - ~~Subpoena~~ Order
 93-270600-000
 Williams v. Remington

ET21088

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-11

TLW #: TLW1303

Date: 3 / 8 / 04Inspector: BLRound Level: 701

- ☒ Measure Headspace min+.004
- ☒ Inspect Take Down Screws for loosening. Center screw 1/8 turn
- ☒ Sear Engagement: 1st. .0297 2nd. .0308 3rd. .030 Ave. .03016 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☐ Trigger Pull: 1st. 4.691 2nd. 4.783 3rd. 4.809 Ave. 4.760 spec- 4.5 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: cam surface, locking lugs, bolt stop signs of some wear
- ☒ Inspect stock for any signs of cracking or other failure: stock cracked at center screw hole
- ☐ Other items of note: _____
- _____
- _____
- _____

TLW1216

Remington Confidential

ET21089