CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Std. Caliber"		
	Project: 241314	TLW #: TLW1689
	Date: 2 122 105	
	Gun Test #	S/N 7/202781
	Round Level: 701	Inspector: <u>BLEE</u>
	Measure Headspace <u>Min † .00 /</u> .	
Ø	Check Takedown Screw Torque @ Disassembly: Frt 30	, Center _ Z&:, Rear/0
a ′	Sear Engagement: 1st. 10252 2nd. 10250 3rd. 10298	Ave. 625 spec020" to.025"
	Reset Sear Engagement if Required: 1st. 2nd.	3 rd . Ave.
	Trigger Pull: 1 st . <u>5.474</u> 2 st . <u>4.993</u> 3 rd . <u>5.16</u> 2	Ave. 5-192 spec- 4 lb. to 5.5 lb.
	Reset Trigger Fall if Required 1st. 2nd.	_3 rd Ave
	Inspect Firecontrol Insert for any signs of cracking or oth	ner
	failure.	
	Other items of	
	note:	
	·	
Torque Takedown Screws @ Reassembly: SPEC- Frt- 50 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.		
		TLW1216
Remington Confidential		

ET22112