

PROJECT # 241314
ENG: MIKE KEENEY
SHOOTER: STEVE WADE

COLD FUNCTION TEST
GUN # A-7 SERIAL # 71126318

TRACKING # TLW 1216V
DATE 9/10/03

- # 1 PLACE GUN A-7 AND 100 ROUND OF AMMO IN FREEZER FOR 15 HOURS AT -20 DEGREE F.
- # 2 TOOK GUN A-7 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO SHOOTING ROOM AND SHOT 20 ROUNDS
LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
CYCLED SAFETY EVERY FOURTH ROUNDS.
PUT GUN A-7 BACK IN FREEZER FOR 2 HOURS.
- # 3 AFTER 2 HOURS TOOK GUN A-7 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
AND SHOT 20 ROUNDS.
LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
CYCLED SAFETY EVERY FOURTH ROUNDS.
PUT GUN A-7 BACK IN FREEZER FOR 2 HOURS.
- # 4 AFTER 2 HOURS TOOK GUN A-7 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
AND SHOT 20 ROUNDS.
LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
CYCLED SAFETY EVERY FOURTH ROUNDS.
PUT GUN A-7 BACK IN FREEZER FOR 2 HOURS.
- # 5 AFTER 2 HOURS TOOK GUN A-7 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
AND SHOT 20 ROUNDS.
LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
CYCLED SAFETY EVERY FOURTH ROUNDS.
PUT GUN A-7 BACK IN FREEZER FOR 2 HOURS.
- # 6 AFTER 2 HOURS TOOK GUN A-7 AND 20 ROUNDS OF AMMO OUT OF FREEZER TO TO THE SHOOTING ROOM
AND SHOT 20 ROUNDS.
LOADING ONE ROUND IN CHAMBER AND THREE ROUNDS IN THE MAGAZINE.
CYCLED SAFETY EVERY FOURTH ROUNDS.

CLEANED AND INSPECTED (EVERYTHING OK)
MALFUNCTIONS

ET22393