BARBER - 5.22.06r0005816

*PROJECT # 241230 ENG: MIKE KEENEY SHOOTER:BOB LEE

HEAT AND HUMIDITY TEST GUN # A-4 SERIAL # 71163352

TRACKING # TLW 1530U DATE 9/8/04

ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

3 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

4 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

5 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE.

CYCLED SAFETY EVERY FIFTH ROUNDS.

PUT GUN A-4 BACK IN ENVIRONMENAL TEST CHAMBER FOR 2 HOURS.

6 AFTER 2 HOURS TOOK GUN A-4 AND 20 ROUNDS AMMO OUT OF ENVIRONMENAL TEST CHAMBER TO SHOOTING ROOM AND SHOT 20 ROUNDS.

LOADING ONE ROUND IN CHAMBER AND FOUR IN THE MAGAZINE CYCLED SAFETY EVERY FIFTH ROUNDS.

7 CLEANED AND INSPECTED (OK)

MALFUNCTIONS 0