PROJECT # 241230 ENG: MIKE KEENEY SHOOTER: BOB LEE

HOT FUNCTION TEST GUN # A-5 SERIAL # 71163350

TRACKING # TLW 1530S DATE 8/3/04

#	_	PLACE GUN A-5 AND 100 ROUNDS AMMO IN PRE-HEATED CHAMBER FOR 15 HOURS AT 120 DEGREE F.
#	2	TOOK GUN A-5 AND 20 ROUNDS OF AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING ROOM AND
		SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FIFTH ROUND.
		PUT GUN A-5 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
#	3	AFTER 2 HOURS TOOK GUN A-5 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING
		ROOM AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FIFTH ROUND.
		PUT GUN A-5 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
#	4	AFTER 2 HOURS TOOK GUN A-5 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING
		ROOM AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FIFTH ROUND.
		PUT GUN A-5 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
#	5	AFTER 2 HOURS TOOK GUN A-5 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING
		ROOM AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN THE MAGAZINE.
		CYCLED SAFETY EVERY FIFTH ROUND.
		PUT GUN A-5 BACK IN PRE-HEATED CHAMBER FOR 2 HOURS.
#	6	AFTER 2 HOURS TOOK GUN A-5 AND 20 ROUNDS AMMO OUT OF PRE-HEATED CHAMBER TO SHOOTING
		ROOM AND SHOT 20 ROUNDS.
		LOADING ONE ROUND IN CHAMBER AND FOUR ROUNDS IN THE MAGAZINE.
L		CYCLED SAFETY EVERY FIFTH ROUND.
L_{-}	L.	CLEANED AND INSPECTED (EVERYTHING OK)
L		MALFUNCTIONS .
		0:3
1		