

## CONFIDENTIAL

Remington Arms Company Inc.  
Research & Development Technical Center  
315 West Ring Road  
Elizabethtown, KY 42701

## Clean &amp; Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-8

TLW #: TLW1530

Date: 7 / 37 / 04Inspector: SWRound Level: 241

- ☒ Measure Headspace Min 4.003
- ☒ Sear Engagement: 1<sup>st</sup>. .0264 2<sup>nd</sup>. .0264 3<sup>rd</sup>. .0262 Ave. .02636 spec-.020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Trigger Pull: 1<sup>st</sup>. 4.916 2<sup>nd</sup>. 5.002 3<sup>rd</sup>. 5.054 Ave. 4.991 spec- 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1<sup>st</sup>. \_\_\_\_\_ 2<sup>nd</sup>. \_\_\_\_\_ 3<sup>rd</sup>. \_\_\_\_\_ Ave. \_\_\_\_\_
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: OK
- ☒ Inspect stock for any signs of cracking or other failure: OK
- ☐ Other items of note: \_\_\_\_\_
- \_\_\_\_\_
- \_\_\_\_\_
- \_\_\_\_\_

TLW1216

Remington Confidential

ET22893