

**Models 700, XP-100 and 40-X**

	Clean and Inspect	Clean, Inspect and Bolt lock feature Removal	Fire control Replacement
Consumer payment to warranty center	\$20	\$20	\$20
Remington Arms Co., Inc. payment to warranty center	\$10	\$20	\$20
Paper Work to Consumer	1. Coupon 2. Denial of Update – get back from customer	1. Coupon 2. Notice of Operation	1. Coupon 2. Notice of Operation

**Models 721 & 722**

	Clean and Inspect	Clean, Inspect and Bolt lock feature Removal	Fire control Replacement
Consumer payment to warranty center	\$20	\$20	N/A
Remington Arms Co., Inc. payment to warranty center	\$10	\$20	N/A
Paper work to Consumer	1. Coupon 2. Denial of Update – get back from customer	1. Coupon 2. Notice of Operation	Notify that gun has been sent back to factory

**Model 600 and 660**

	Clean and Inspect	Clean, Inspect and Bolt lock feature Removal	Fire control replacement due to maintenance	Fire control Replacement due to recall
Consumer payment to warranty center	\$20	\$20	\$20	Free
Remington Arms Co., Inc. payment to warranty center	\$10	\$20	\$20	\$40
Paper work to Consumer	1. Coupon 2. Denial of Update – get back from customer	1. Coupon 2. Notice of Operation	1. Coupon 2. Notice of Operation	1. Coupon 2. Notice of Operation