

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-14

TLW #: TLW1530

Date: 8 / 30 / 04Inspector: BNRound Level: 741

- ☒ Measure Headspace Min 4.006
- ☒ Sear Engagement: 1st .0336 2nd .0338 3rd .0337 Ave. .0337 spec. .020" to .025" 83
- ☐ Reset Sear Engagement if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Trigger Pull: 1st 4.053 2nd 4.009 3rd 4.053 Ave. 4.038 spec. 4 lb. to 5.5 lb.
- ☐ Reset Trigger Pull if Required: 1st _____ 2nd _____ 3rd _____ Ave. _____
- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs normal wear
- ☒ Inspect stock for any signs of cracking or other failure. Small crack 45° from recoil lug shooter's left only
- ☒ Other items of note: OK Fire control bracket screw loose (retighten)

TLW1216

Remington Confidential

ET23014