

Colonial Plastics, Inc.

108 South Foushee Street
Richmond 20, Virginia
P. O. Box 518MANUFACTURERS OF
LIGHT CONTROL DRAPERIES
STAGE CURTAINS

June 20, 1963

Remington Arms Company
Illion, New York

Gentlemen:

I have one of your new Remington .221 Fireball Pistols and I will appreciate any information that you have available as to the change of the point of impact as the barrel warms. The groups with hand loads at 130 yards are excellent but there seems to be no consistency about the first two or three shots fired from a cold, clean barrel.

Also I should like to know if it is possible to purchase the weaker extractor spring, as the one that has been used in my pistol, will throw the fired case ten to twelve feet.

Cordially yours,


COLONIAL PLASTICS, INC.
Carl E. Lindenmayer

CEL/sl

remove ejector ~~by~~ & ejector spring
by driving return pin out of ball - using a
small suitable punch. Cut off 1 to 3 coils of
the ejector spring - replace in reverse order
& test to gain satisfaction.

