HAMPING MAD. (INEA 1884)

LAUMENCE SELLING, M.D. (INEA 1884)

MERL I. MARGAAGO, M.D.

THE PORTLAND CLINIC
PHYSICIANS AND SURGEONS
1216 SOUTHWEST YAMMILL STREET
PORTLAND, OREGON 97205

MERIC L. MARGASON, M.D.
ANTHUR L. ROGERS, M.D.
CORPON PREWITT, M.D.
PHILIP SELLING, M.D.
GEORGE A. SOYLSTON, M.D.
ANTHUR G. ENICREEN, M.D.
WAYNE G. ENICREEN, M.D.
WAYNE G. ENICREEN, M.D.
DOWALD E. GLSON, M.D.
L. WILLIAM LAREON, M.D.
JOHN M. BLLISON, M.D.

JOHN K, MARTIN, JR., M.D.

December 13, 1965

JOHN R. MAND, M.D.
ALLEM M. BOYDEN, M.D.
ALTHUR W. SULLIVAR, M.D.
AMBROSE B. SHIELDS, M.D.
JOSEPH W. MADAL, M.D.
L. S. CASPERS DN, M.D.
JAMES A. WOOD, M.D.
GEORGE E. CHAMBERLAIN, M.D.
DARRELLA W. LANDREY, M.D.
DARRELLA W. LANDREY, M.D.
ENKLET A. WATERMAN, M.D.

ADMINISTRATOR

Remington Arms Co., Inc. Rifle Development Department Bridgeport, Conn.

Dear Sirs:

This last elk hunting season I used the Remington, Model 600 Magnum and found it very effective. However, I also found it the most dangerous rifle I have ever carried on my shoulder.

When I carried it by the sling over the shoulder the safety apparently caught on clothing and went from the safe to the fire position. At least half a dozen times the first morning, on checking, I found it was on "fire" after being placed on "safe".

The thumb piece on the safety of this rifle is much too large, and I am sorry that you did not use the same type safety that you used on the Model 700, which is perfectly secure when carried over the shoulder.

After that first morning I taped the safety on "safe" with a piece of plastic tape which would break with pressure when I needed to fire. The only plastic tape available in the hunting camp was bright green, and everyone who saw the rifle wondered what the bright green tape was for, and I had to explain to them why it was on and that this was for the safety of myself and my companions.

If from an engineering standpoint you feel a stronger spring can be placed to maintain the safety on "safe" please let me know so that I may return the rifle to you. Otherwise I think I will simply grind down the big knob to a smaller size.

ALR-mr

1-11-