

<u>MODEL</u>	<u>LAST SERIAL NO.</u>	<u>DATE OF LAST SERIAL NO.</u>	<u>FIRST SERIAL NO.</u>	<u>DATE OF FIRST SERIAL NO.</u>
580)				
590) Series				
540)				
N/66				
788	068460	10/11/68	6,000,000	12/3/68
742) Series				
760)				
1100				
870				
11-48				
550-1				
514				
40-XB	38742B	11/14/68	38743B	-
700)	387347	11/21/68		
660) Series	131552	11/26/68	6200000	11/26/68
XP-100	11000	4/15/68	7500000	12/4/68
552)				
572)				

DJAnderson:I
12/12/68

CURRENT MODEL
SERIAL NUMBERING SYSTEM

MODEL

580 Series)
590 Series)
540 Series)

550-1

552)
572)

514

40-XB

----- B

N/66

788

6,000,000 to 6,199,999

700)
660)

6,200,000 to 6,899,999

742)
760)

XP-100

7,500,000 to 7,509,999

1100

870

11-48

DJA:I
11/22/68

DJA
12/12/68

*SMA
Trouble with loading magazine*

bcc J. P. McAndrews) In
F. E. Morgan) Tur
G. M. Calhoun

File Copy

December 9, 1968

RECEIVED

DEC 9 1968

G. M. CALHOUN

Lt. Gen. R. K. Mellon
Wm. Penn Place Building
Pittsburgh, Pennsylvania 15219

Dear General Mellon:


It was a pleasure to talk to you the other night and to be present when you were given such a well-deserved award.

I appreciated your comments about the M/600 because, as you can imagine, we are quite proud of this rifle. I have made some inquiries and find other people as surprised as I was that you have had feeding trouble. They feel this may be an adjustment problem with your particular rifle.

If, at your convenience, you would like to give your gun to Rudy Etchen, he could make arrangements with our F. E. Morgan to have it returned to Ilion for checking and adjustment if necessary.

We appreciate your continued interest in Remington and will always value your comments and suggestions.

Sincerely yours,



Philip H. Burdett
Vice President and
Assistant General Manager

PHB:m

2-6-69

This rifle arrived yesterday. In careful check it seems to be perfect in every respect except that receiver ejection port has been further cut away to accommodate some special scope and mount that may be contributing to the "trouble with loading magazine" described.

I had Bob Kelly call T.C. Williams at Pittsburgh who has the scope and is sending it in to us so can recheck, and perhaps be in position to come up with a suggestion.

S.M.-Alvis