

Copy to FT Plumbett

cc: R. L. Hall
✓ F. Millener
M. Walker/J. Brooks
F. E. Morgan

May 18, 1973

P. Velasco

Model 700 and Model 541 Firearms
AUSTRALIA

In respect to the above models, the present trigger assembly is not suitable for the Australian market.

Modifications have been made to these products held in the Customs warehouse in Australia. Therefore, you are requested to initiate a procedure whereby our orders for Australia for these models indicate that modifications must be made to these firearms prior to shipment.

By copy of this letter we are requesting that a procedure be set up at Ilion to handle this correction. John Brooks at Ilion is familiar with the requirements and initiated the instructions for making this repair.

I believe this can be handled in the same manner as we installed the orifice control screw for the Model 1100.

Your comments will be appreciated.

E.S. Cipcer/ajf

E.S. Cipcer