Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

## Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue Anchorage, Alaska 99501 (907) 272-1570

In Anchorage Bill's Gun Shop 8729 Lake Otis Parkway (907) 349-1312

In Fairbanks Dixon's 261 College Road Anchorage, Alaska 99507 Fairbanks, Alaska 99701 (907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

# IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

# Owners of the above guns should contact one of the following gunsmiths:

In Honolulu Honsport, Ltd. 1365 Colburn Street Honolulu, Hawaii 96817 (808) 833-3026 or (808) 949-5591 In Honolulu The Thom Company, Ltd. King & Smith Streets Honolulu, Hawaii 96817 (808) 538-6764

In Honokaa Ka Pu Kapili P.O. Box 745 Honokaa, Hawaii 96727 [808] 775-0244

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

# IMPORTANT MESSAGE TO OWNERS OF REMINISTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PESTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any

XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected—and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

in all states except Georgia (toll free):

1-800-241-8444—ask for operator 61

In Georgia (toll free):

1-800-282-1333—ask for operator 61

In Canada (collect):

519-621-7271

maraners

to smoke in spite of its fearful fumes, my mother's hatred of the habit, and the expense to my non-existent budget. But somehow the idea of sitting there, pulling tentative, practice smoke rings until my tongue blistered added the final touch to my vision of myself as a would-be mountain man. By just closing my eyes I could be dressed in buckskin—fringed, of course—and palavering in pretty good fashion complete with the two or three gestures of "linger talk." I had picked up in my brief encounter with the Boy Scous.

In those days you could buy at any good country general store a pair of what was known as "over-the-knee" boots. How far over depended on how tall you were, but they were never over enough for wading in anything more than a rivulet. Any retrieving chores in my wind-sheltered pothole necessitated going in over the tops; why I didn't just take the boots off and wade wet escapes me now, but I know I never did. No doubt getting wet and a little bit cold only enhanced the mood of wilderness and adventurepart and parcel of being out on your own, surviving against the elements -with home and a glowing wood burning kitchen stove a brisk hour's walk away, just the right distance in the dark to have its owl-calling moments of chilling thalls before the yellow lights of the farmhouse appeared with their promise of warmh. security, and a homemade meal.

THEO & STREAM JANUARY 1979

My pondhole delivered the occasional duck before freezing over early in November, and now and then a gray squirrel or rabbit, but that was the small end of its purpose. To a yearing farmboy with an imagination that hordered on runaway, it served magnificently as a frontier: at times an ocean, more often an unnamed mountain bivouac, or the headwaters of a wilderness river. It lent credence, in its way, to the visious of Hudson's Bay, the Rocky Mountains, and eager comparisons with the lives of Carson and Boone, Lewis and Clark, Bridger and Green. My ducks were messengers from places unknown and truly wild, passing through from what I believed to be moose and caribou country to an equally believed tropics filled with anneondas and bushmasters-how I wished then, and still do, that I could see for myself the lands they saw and lived in. And their just being there, those pintails and blacks, in from of my oak and hazel and cedar blind, created a belief in things I could only dream about-their wines whispered that all these things were real and true; that they had seen and known places and creatures that would beggar my wildest dreams.

My visions of exploring these wondrons tracts never failed to include the company of what was the most longed-for thing to my life—an exact duplicate of my father's gun Gorbidden to me then, of

course); that most exquisite piece of machinery known as a Winehester model 97 hammer pump. With this in hand, I would be fearless, unconquerable, and completely selfsufficient . . . anywhere. I'd sneak it out and shock it when no one was around and marvel at how perfect it sounded as the various rods and slides drew a shell from the magazine up into the chamber, the bolt slid the hammer back as slick as anything, and it all closed with consomate authority and sat poised to strike with a power that to me was akin to lightning. Then I would work it empty again, case the hammer back to half, the way Pop left it, wipe it off, and place it back in the closet where it always sat,

Before I was hig enough to handle it. Pop traded the 97 for another pump he never liked as well. And then we moved. The fact that the pondhole and the pump are gone are indisputable. But I still have my pintails and the occasional black... and have now and then gone where, no doubt, some Indian has walked before. The dreams have shrank somewhat and the night-calling owls bring another kind of chilling thought... a moment beyond the help of even Pop's old model 97. But the husbing sound of wings can still evoke that timeless magic and as I watch them slant above my hiding place. I still wonder, as always, what it was they saw yesterday and what they will see tomortow.

93

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

# Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue (907) 272-4570

In Anchorage Bill's Gun Shop 8729 Lake Otis Parkway Anchorage, Alaska 99501 Anchorage, Alaska 99507 Fairbanks, Alaska 99701 (907) 349 1312

In Fairbanks Dixon's 261 College Road (907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

In the continental United States, write to: Remington Arms Company, Inc., 939 Barrum Avenue, Bridgeport, CT 06602.

almost a marine and

# TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected—and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except Georgia (toll free):

1-800-241-8444—ask for operator GL
In Georgia (toll free):

1-800-252-1535—ask for operator GL
In Canada (collect):
519-621-7271

Another important message to all gun owners.

Much has been written on firearms safety in general, and gun safeties, in particular, but we feel that a most incisive statement is contained in the NRA Hunter/Safety Handbook: "No hunter should depend wholly on the safety to prevent accidental firing. The safety is meant only to supplement proper gun handling."

Remington Arms Company, Inc.

Rilliamon

**BARBER - PRESALE R 0105561** 

, i i i

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

# Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue Anchorage, Alaska 99501 (907) 272-4570

In Juneau C & 5 Gun Room 9½ Mile Glacier Highway Juneau, Alaska 99803 Telephone: 907-789-2680 Mailing address: P.O. Box 2415 Note: ship regular mail, NOT U.P.S.

In Anchorage Bill's Gun Shop 8729 Lake Otis Parkway Anchorage, Alaska 99507 (907) 349-1312

In Fairbanks Dixon's 261 College Road Fairbanks, Alaska 99701 (907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.