

Approved Version

IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected - and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except ^{Gaorgia} ~~Connecticut~~ (toll free):

~~1-800-243-2670~~

800-241-8444 — ask for Operation 51

In ^{Gaorgia} ~~Connecticut~~ (toll free):

~~1-800-972-9379~~

800-282-1333 — ask for Operation 51

In Canada (collect):

519-621-7271