

Sportsmen's Equipment Company

"DAN DWYER"

GUNS and FISHING TACKLE

915 W. WASHINGTON STREET
SAN DIEGO, CALIFORNIA 92103

(714) 296-1501



John Dwyer
 Remington Arms Company, Inc
 Ilion, N.Y. 13357

ATT: Mr. Vic Rostokar

Dear Vic — While I'm working on it, and it is fresh in my mind; I had better write this. I have meant to before this but something else always interferes.

This is one of several Trigger difficulties of this same kind in recent months.

The customer brought this Mod 700 to me complaining that blamed thing fired when he released the safety. It only happened when the outside temperature was very cold. He had been hunting in Colorado at high altitude.

When I took it apart, I found it badly gummed up with WD-40 (confirmed by questioning him).

Nothing wrong with the Trigger except his own tampering, the gummy WD-40 and the cold weather.

He had pulled the Trigger when the safety was on, the gummy WD-40 held it retracted and when the safety was switched off the inevitable happened:

I've had several of these same cases in recent months. All Triggers were gummed up with rust preventatives.

Please inform your engineering people.

Sincerely

Daniel I. Dryer, Sr.

Daniel I. Dryer, Sr.

Romington recommended Gums.