

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

CHUCK

PETERS

CO

See G.D.C.

CC: R. Long
W. Blair
D. Anderson
L. Ferreira

XC: LB Bosquet

9-9-82

September 7, 1982

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY"

TO: J. Rogers

FROM: D. Ricci

SUBJECT: W/7 LWT Release Advise

Have / Hal
Be aware that
purchased parts are not
proceeding as well as
they should

Below is a list of all the new purchase parts required for the Model 7.9/8/82
 Reviewing the release advise report, it appears that the information
 is not consistent within this family of parts, as follows;

PART NO.	PART NAME	Vendor Genuine Shipped	DUE DATE PER RELEASE ADVISE
Yes? 91845	Trigger Guard Plate	NO	not released SQUARE
Yes 91846	Magazine Spring Retainer	NO	not released ALMED, "IFFY" & WKS ARE
NO 91851	Safety	NO	not released SQUARE
Yes 92227	ON COCK Bolt Handle		9-27 HARD IMPOT A JUNE
Yes 92247	Front Sight Ramp Screw	N/A	10-11 SQUARE SCREW, "IFFY"
Yes 92248	Rear Guard Screw	N/A	10-11 CONN. MTH. H HCH HAKED, CK MTH JN
NO 92249	Trigger Guard	NO	10-4 H/P, SQUARE NOT IMPACTED
Yes 92250	Floor Plate Latch Spring		no requirements NEWBORN
	10,000 received not inventoried yet		
Yes? 92251	Bolt Stop Release	NO	10-4 ALMED, & WKS ARE
A/J 92253	Bolt Stop	A/J	10-11 H/P
	Part has not been transmitted to add use W/600 #15412, therefore Vendor (H/P) del. is questionable.		
NO 92255	Floor Plate Cover	NO	no requirements ALMED, WKS ARE
NO 92256	Floor Plate Base	NO	no requirements H/P
NO 92454	Magazine Follower	NO	not released ADALL, NOV 10/4

It would appear that we want all Production parts on hand in early Oct., though the necessary planning reports are not all released.

Please review and advise. No orders have been issued, nor have I spoken with the vendors on these abbreviated leadtimes.

DEFINITION

NO REQUIREMENTS — APPARENTLY NO LINK TO MASTER SCHEDULE
 NOT RELEASED — APPARENTLY LINKED BUT NOT RELEASING

DDR/y