

File M/700 Bolt Lock

FINISHED GUN QUALITY

Week Ending 3/12/82

Total Guns	Demerit Category				Total Dem's	Week DPU	4 Wks. Avg.	Yr. to Date
	100	50	10	1				
127	0	1	23	17	297	2.3	1.9	2.1

50 DEMERIT ITEMS (1)

<u>M/700</u>	1. Wrong instruction folder (old style safe; new style folder).
--------------	---

10 DEMERIT ITEMS (23)

18.1% Defective

16.2% - 4 Wks. Avg.

19.0% - Yr. to Date

NUMBER LAST
12 MONTHS

<u>M/870</u>	1. White recoil pad spacer cracked	1
	2. Bulge at muzzle end of Barrel	1
	3. Ejector spring cracked	6
<u>M/1100</u>	Same (1. Excess steel margin Stock to Receiver, excess wood margin Stock to Receiver	25
	Gun (2. Fore End peeling	1
	3. Dirty recoil pad	2
	4. Excess wood margin Stock to Receiver	26
	5. Barrel pitted on side	2
	6. Feed latch fell out	20
	7. Excess wood margin Stock to Receiver, excess steel margin Stock to Receiver	27
	8. Excess wood margin Stock to Receiver	28
	9. Excess steel margin Stock to Receiver	13
<u>M/700</u>	1. Poor finish on grip cap	11
	2. Orange peel on Stock	3
Same	(3. Finish lifting on grip cap	1
Gun	(4. Poor polish on Receiver	8

(over)