

cc: E.F. Sienkiewicz
J.E. Preiser
E.G. Larson
R.G. Sherman
J.H. Chisnall

December 11, 1978

Mr. O.K. Baxley
Vice President for Finance
Lamar University
P.O. Box 10003
Beaumont, Texas 77710

Dear Mr. Baxley:

Examination has been completed on your returned Model 700 ADL 6mm caliber rifle, serial number 307270.

We found the trigger assembly to be well within manufacturing specifications and we could not duplicate the problem that you had experienced. However, we did find excessive oil within the trigger assembly and strongly recommend that oil be used sparingly on the rifle with no lubrication added to the trigger mechanism.

In most of our investigations, concerning the problem that was experienced, we have found that the safety was pushed to the fire position with a finger on the trigger.

As a gesture of good will, we are replacing the entire trigger assembly, at no charge, and the rifle will be returned via Blue Label U.P.S.

Thank you for having afforded us this opportunity to be of service.

Sincerely,

E.F. Sienkiewicz, Supervisor
Firearms Product Service

EFS:tpf

PLAINTIFF'S
EXHIBIT

3134

AL 0024700

10f1