



# REMINGTON ARMS COMPANY, INC.



SPORTING FIREARMS  
TRAPS  
POWDER METAL PARTS  
ILION, NEW YORK  
AMMUNITION, BRIDGEPORT, CONNECTICUT  
LONOKE, ARKANSAS

MANUFACTURERS OF  
SPORTING FIREARMS, AMMUNITION  
TRAPS TARGETS  
ILION, NEW YORK 13357  
TELEPHONE (516) 894-9961

PETERS CARTRIDGE DIVISION  
BRIDGEPORT, CONNECTICUT  
TARGETS, ADA, OKLAHOMA  
ATHENS, GEORGIA  
RINDLAY, OHIO  
CABLE—HARTLEY, BRIDGEPORT

August 30, 1984

Mr. Dick Key  
P.O. Box 303  
Mineral Bluff, Georgia 30559-0303

Dear Mr. Key:

Your letter of July 24, 1984 that was addressed to our Bridgeport, Connecticut facility, regarding the accidental firing you experienced with your Model 700 22-250 Rem. caliber rifle, serial number A6850932, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described, as it is not characteristic of the Model 700 rifle.

Generally, the type of malfunction you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or, from pressure being inadvertently applied to the trigger at the instant the safety is released.

Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Company, Inc.  
Attn: Mr. J.A. Stekl  
Supervisor, Product Service  
Ilion, New York 13357

Upon receipt, we will thoroughly examine the rifle and, if it is found to be factory faulty, we will assume responsibility for your unfortunate mishap.

Thank you for bringing this matter to our attention and for affording us this opportunity to be of service to you.

Sincerely,

J.A. Stekl, Supervisor  
Product Service

JAS:tpg