

RECEIVED

NOV - 3 1984 11-19-84

J. A. STEKL

Dear Mr. Stekl,

To say the least I am disappointed that Remington Arms is unwilling to take responsibility for the rifle I sent you misfiring. Apparently eyewitnesses to the incident and the assurance of my gunsmith that this model rifle has been sent to him before for just this problem are not sufficient.

I certainly would like the new trigger assembly installed allowing me to unload while in the "safe" position. I find it curious that you now have such a safety mechanism if the mechanism on my rifle was as satisfactory as your examination claims. Why change a good system? Please make the change and return the

rifle to me (Model 700 ADC
22-250 #A 6850932

Dick Key
PO Box 309
Mineral Bluff, Georgia -
30559
404-374-5894