

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE 013 894-9961

March 11, 1983

8.5 # 1152

Mr. Phil Hucks
Box 25
Mound Valley, Kansas 67354

Dear Mr. Hucks:

Your recent letter that was sent to our Bridgeport, Connecticut facility, regarding the accidental firings you have experienced with your Model 700 30-06 caliber rifle, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you described, as it is not representative of Remington quality, nor characteristic of the Model 700 rifle.

Generally, the type of incident you described results from either improper adjustment of the trigger assembly outside our factory, foreign material, such as excessive lubrication, inside the trigger assembly, or, from pressure being inadvertently applied to the trigger while the safety is in the "fire" position.

Please, at your convenience, return the rifle via insured and collect transportation, to:

Remington Arms Company, Inc.
Arms Service Division
Ilion, N.Y. 13357

Upon receipt, we will have our technicians thoroughly examine your rifle and, if it is found to be factory faulty, any necessary repairs or other corrections will be made on a no-charge basis. If otherwise, a repair quotation will be sent for your approval prior to effecting any repairs.

Thank you for bringing this matter to our attention, Mr. Hucks, and for having afforded us this opportunity to be of assistance to you.

Sincerely,

J.A. Stakl, Supervisor
Firearms Product Service

2-23

JAS:tpg